UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0135 Expires November 30, 2000

5. Lease Serial No.

NM	\sim	1	\sim	Λ	_
NIVI	1/	- 1	1	ч	-3
TALL	U 4	_	v	_	_

SUNDRY NOTICES AND REPORTS ON WELLS			NMO21095			
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.			6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRIPLICATE - Other instructions on reverse side				7. If Unit or CA/Agreement, Name and/or No.		
1. Type of Well	Dine S Abane	don (9707	1250000	8. Well Name and No.		
Oil Well Gas Well Other Plug & Abandon			- 🛊 े े	Yates "A" #6		
2. Name of Operator Yates Petroleum Corporation		9. API Well No.				
3b. Phone N		3b. Phone No. (included 505-748	HIGEYAED	30-015-04481 10. Field and Pool, or Exploratory Area		
4 Location of Well (Footage, Sec., T., R., M., or Survey Description)				Loco Hills-Q-GB-SA		
1650' FNL & 2310	' FEL of Section 6	5-T18S-R30E		11. County or Parish, State		
Unit G, SWNE		$=\frac{2}{2}u_{i}$	84957817	(d)		
12. CHECK AP	PROPRIATE BOX(ES) TO	INDICATE NATU	RE OF NOTICE,	REPORT, OR OTHER DATA		
TYPE OF SUBMISSION		T	PE OF ACTION			
	☐ Acidize	Deepen Deepen	Production (St	tart/Resume)		
Notice of Intent		Fracture Treat	Reclamation	Well Integrity		
·	Casing Repair	☐ New Construction	Recomplete	Other		
Subsequent Report		Plug and Abandon	Temporarily			
Final Abandonment Notice		Plug Back	Water Dispos	f any proposed work and approximate duration thereof. true vertical depths of all pertinent markers and zones.		
anchors. Dug out BOP. Rigged up f 10-23-2002 - Rigg wireline. RIH wi POOH. Shut well 10-24-2002 - RIH mud. POOH with the POOH and rigged of Squeezed with 45 10-25-2002 - POOH 1058'. POOH. RIH with packer and Pressured up to	d in and rigged up cellar. Nippled loor and 2-3/8" to led up wireline. Ith 2-3/8" workstr in for night. Wo with tubing and to lown wireline. RI sacks Class C Neal with packer and the look perforated and tubing. Release 1000 psi. Release	down swedge ubing equipme RIH but could ing to 2790'. C. agged plug at wireline. Fill with packer t cement. Showing. Rigg 7" casing at aged with 50 cement.	and install nt. not get paragrams Spotted 30 2515'. Ci RIH and performand tubing nut well in ged up wirel 525'. POOH sacks Class OOH with pac	ing equipment. Installed two ed 7" wellhead. Nippled up st 930'. POOH and rigged down 0 sacks Class C Neat cement. rculated hole with plugging orated 7" casing at 1235'. to 933'. Set packer. for night. WOC. ine. RIH and tagged plug at and rigged down wireline. C Neat cement. WOC 4 hours. ker. Rigged up wireline. RIH		
14. I hereby certify that the forego Name (Printed/Typed)	ing is true and correct	Trut.		,,		
DONNA CLACK Title REGULA			REGULATORY	COMPLIANCE		
Signature	ma Clack	Date	11-15-02			
	THIS SPACE	FOR FEDERAL OR	STATE OFFICE I	JSE TO THE TOTAL PROPERTY OF THE TOTAL PROPE		
Approved by Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.						
Title 18 U.S.C. Section 1001 and States any false, fictitious or frauc	Title 43 U.S.C. Section 1212, mal	ke it a crime for any pers s as to any matter within	on knowingly and will its jurisdiction.	fully to make any department or agency of the United		
Anni Car	end so in pinning of lines. So restoration in occupated	Services Ser	ied for record - 1	LES BABYAK PETROLEUM ENGINEER		

YATES PETROLEUM CORPORATION Yates A #6 Section 6-T18S-R30E Eddy County, New Mexico

SUNDRY NOTICE CONTINUED:

and tagged plug at 386'. POOH with wireline. Shut well in for night. 10-26-28-2002 - RIH with wireline and perforated 7" casing at 60'. POOH and rigged down wireline. Rigged down tubing equipment and floor. Nippled down BOP and 7" casinghead. Installed 7" X 2" swedge with valve. Squeezed with 60 sacks Class C Neat cement. WOC 4 hours. Did not tag. Squeezed with 50 sacks Class C Neat cement. Shut well in for night. WOC.

10-29-2002 - Tagged plug at 32'. Circulated 20 sacks Class C Neat cement from 32' to surface. POOH with tubing. WOC 4 hours. Cut off wellhead. Rigged down pulling unit and plugging equipment. Installed regulation abandonment marker. PLUGGED AND ABANDONED Donna Clack

- FINAL REPORT. Plugging completed 10-28-2002.