

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

NM 021095  
(Under Instructions)  
Artesia, NM 88210

Form approved.  
Budget Bureau No. 42 R1424  
5. LEASE DENIGATION AND SERIAL NO  
NM 021095  
6. INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> <u>WTW - TA</u>		7. UNIT AGREEMENT NAME <u>LOCO HILLS FLOOD</u>	
2. NAME OF OPERATOR <u>NEWMONT OIL COMPANY</u>		8. FARM OR LEASE NAME <u>YATES "A"</u>	
3. ADDRESS OF OPERATOR <u>P. O. BOX 1305 ARTESIA, NEW MEXICO 88210</u>		9. WELL NO. <u>9</u>	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface <u>990 FNL 911 FWL Sec. 6-18-30</u>		10. FIELD AND POOL, OR WILDCAT <u>LOCO HILLS (Q. G. SA)</u>	
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <u>Sec. 6-18-30</u>	
15. ELEVATIONS (Show whether DF, RT, CR, etc.) <u>3550'</u>		12. COUNTY OR PARISH <u>Eddy</u>	
		13. STATE <u>New Mexico</u>	

RECEIVED

SEP 1 1982

O. C. D.  
ARTESIA, OFFICE

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
(Other) <input type="checkbox"/>	

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

1. Pull tubing and packer
2. Spot sufficient cement across producing interval to tie back to production string casing seat, or set bridge plug near casing seat and cap with 25 sack cement plug.
3. Perforate base of salt @ 1100' and squeeze with 50 sacks cement leaving 100' plug in casing.
4. Perforate top of salt @ 470' and squeeze with 50 sacks cement leaving 100' plug in casing.
5. Set 15 sack cement plug at surface tying surface and production casing together.
6. Erect permanent well marker

Note: (A.) Your office will be notified 24 hrs. prior to operations.  
(B.) All plugs will be verified  
(C.) Hole will be loaded between all plugs with 10# mud  
(D.) We do not plan to pull any casing.

RECEIVED  
JUL 30 1982

OIL & GAS  
U.S. GEOLOGICAL SURVEY  
ROSWEIL, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Area Manager

DATE 7/28/82

(This space for Federal or State office use)

APPROVED BY (Orig. Sgd.)

PETER W. CHESTER

TITLE

DATE

CONDITIONS OF APPROVAL

AUG 31 1982

FOR

JAMES A. GILLHAM  
DISTRICT SUPERVISOR

See Instructions on Reverse Side