

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
Artesia, NM 88210

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985
LEASE DESIGNATION AND SERIAL NO.

NM 021095

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. NAME OF OPERATOR Yates Petroleum Corporation	2. ADDRESS OF OPERATOR 207 South 4th St., Artesia, NM 88210	3. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 990 FNL & 911 FWL, Sec. 6-T18S-R30E	4. PERMIT NO.	5. ELEVATIONS (Show whether DF, RT, GR, etc.) 3550' KB	6. IF INDIAN, ALLOTTEE OR TRIBE NAME	7. UNIT AGREEMENT NAME	8. FARM OR LEASE NAME Yates "A"	9. WELL NO. 9	10. FIELD AND POOL, OR WILDCAT Loco Hills-Q-G-SA	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Unit D, Sec. 6-18S-30E	12. COUNTY OR PARISH Eddy	13. STATE NM
--	--	--	---------------	---	--------------------------------------	------------------------	------------------------------------	------------------	---	--	------------------------------	-----------------

18. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) <input type="checkbox"/>	

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Propose to plug well as follows:

1. Spot sufficient cement across producing interval to tie back 50' into production casing shoe. Tag plug.
2. Isolate Queen formation from overlying zones with 100' cement plug. Top of Queen is at 2288'; top of cement is at 2128'.
3. Perforate 50' below base of salt at 1150' and squeeze with 50 sx cement, leaving 100' plug in casing. Tag plug.
4. Perforate 50' above top of salt at 420' and squeeze with 50 sx cement, leaving 100' plug in casing. Tag plug.
5. Set 50' surface plug and install regulation abandonment marker. Both sides of csg.

NOTE: 1) NOTIFY BLM, CARLSBAD, NM, (887-6544) 24 HOURS PRIOR TO BEGINNING WORK.

2) Mud between plugs to be 10#/gallon mud-laden fluid.

18. I hereby certify that the foregoing is true and correct

SIGNED Guarinta L. Gordon

TITLE Production Supervisor

DATE 11-26-85

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE 12-10-85

*See Instructions on Reverse Side