

DEP

SUNDRY

(Do not use this form for Use "2")

1. OIL WELL ☒ GAS WELL ☐ ☐

2. NAME OF OPERATOR

SKEL

3. ADDRESS OF OPERATOR

P. O. Box 730

4. LOCATION OF WELL (Report to See also space 17 below.)
At surface

1980' FWL

14. PERMIT NO.

--

16. **Ch**

NOTICE O

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

17. DESCRIBE PROPOSED OR COMPLETED work. If well is pertinent to this work.)*

1. Moved in and rig
2. Pulled rods and
3. Ran Collar Log.
4. Perforated 5-1/2" 3306', 3314', 33341', 3574', 3588',
5. Treated down tub regular acid and
6. Treated down 5-1. water, 20,000# 2
7. Ran tubing and p
8. Ran tubing and r
9. Well pumped 10 b
10. Well returned to

Workover
Well

**UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY**

SUBMIT IN (Other instructions on reverse side)

LOCATE (Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 029420 (a)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Shelly Unit

8. FARM OR LEASE NAME

Shelly Unit

9. WELL NO.

94

10. FIELD AND POOL, OR WILDCAT

Grayburg Jackson

11. SEC., T., R., E., OR BLK. AND SURVEY OR AREA

Sec. 28-17S-31E

12. COUNTY OR PARISH 13. STATE

Eddy

New Mexico

NOTICES AND REPORTS ON WELLS

Proposals to drill or to deepen or plug back to a different reservoir.

NOTIFICATION FOR PERMIT—" for such proposals.)

OIL COMPANY

Hobbs, New Mexico 88240

Clearly and in accordance with any State requirements.*

1980' FWL Sec. 28-17S-31E

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3800' DF

Appropriate Box To Indicate Nature of Notice, Report, or Other Data

ATTENTION TO:

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

PERFORMATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any operationally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

**up Workover Rig.
ing.**

8 casing with one shot per interval at the following depths: 3294', 3355', 3362', 3372', 3380', 3429', 3438', 3458', 3475', 3500', 3508', and 3615', a total of 18 shots.

into 5-1/2" OD casing perforations 3294-3615' with 1250 gallons 15% ball sealers.

OD casing into perforations 3294'3615' with 2000 gallons treated 8 sand and 8 ball sealers.

ed retrievable bridge plug.

als oil in 24 hours.

nducing status 12-25-1967.

**Commenced - 12-13-1967
pleted - 12-16-1967**

18. I hereby certify that the foregoing is true and correct

SIGNED (Signature)

(This space for Federal or State use)

APPROVED BY
COMMISSIONER OF APPROVAL

DEC 28 1967

**R. L. BECKMAN
ACTING DISTRICT ENGINEER**

is true and correct

(Signature)

Office use)

ANY:

TITLE **District Superintendent**

DATE **December 26, 1967**

TITLE

DATE

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.