

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPlicate
(Other instructions on reverse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

45F

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

MAY 23 '88

O. C. D.

EXTENSION OFFICE

5. LEASE DESIGNATION AND SERIAL NO.	LC-029420 (b)
6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
7. UNIT AGREEMENT NAME	Skelly Unit
8. FARM OR LEASE NAME	
9. WELL NO.	94
10. FIELD AND POOL, OR WILDCAT	Grayburg-Jackson SR-QN-GB-SA
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA	Sec. 28, T17S, R31E
12. COUNTY OR PARISH	Eddy
13. STATE	NM

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3800' DF

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANE

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

Temporary Abandon

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Reclassify from SI-0 to TR-0 (Held for Remedial Work), effective 4/4/88.

- 1) MIRU pulling unit. Install BOP. Pull tubing.
- 2) By wireline, RIH with gauge ring and junk basket to 3280'. POH. RIH with CIBP and set at 3280'. (Top perf at 3294', 5 1/2" casing.) Dump 35' of Class "H" cement on top of CIBP.
- 3) RIH with tubing. Load hole with inhibited water. POH.
- 4) Rig down pulling unit.
- 5) Test 5 1/2" casing to 500 psi-Ok. Pressure chart attached.

18. I hereby certify that the foregoing is true and correct

SIGNED

Ja Heac

TITLE

397-3571

Hobbs Area Superintendent

DATE

5/10/88

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR FILING

5/19/89

*See Instructions on Reverse Side

SJS
CAPITOL, NEW MEXICO