n 9-8018			Budget Bu Form App		• 42-R358.4.
Teb. 1991	(SURMIT II	(SUBMIT IN TRIPLICATE)		Las	Crucos
	UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY		Lease No. 029415-A		415-A
			Unit		
			01110	••••••	
SUNDRY	NOTICES AN	D REPORTS O	N WELI	.S	
OTICE OF INTENTION TO DRILL	TICE OF INTENTION TO DRILL		R SHUT-OFF		
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING			
NOTICE OF INTENTION TO TEST WAT	rer shut-off	SUBSEQUENT REPORT OF ALTERING CASING			
NOTICE OF INTENTION TO RE-DRILL	OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DR	ILLING OR REPA	IR	
NOTICE OF INTENTION TO SHOOT OF	R ACIDIZE	SUBSEQUENT REPORT OF ABANE	DONMENT		
NOTICE OF INTENTION TO PULL OR	ALTER CASING	SUPPLEMENTARY WELL HISTORY			
NOTICE OF INTENTION TO ABANDON	WELL	-			
(INDIC/	ATE ABOVE BY CHECK MARK NAT	TURE OF REPORT, NOTICE, OR OTHE	R DATA)		
		<u></u> <u>M</u>	arch 25,		, 1964
Bueloote 1141					
Puckett "A"	tod 1345 ft from \int	N line and 1345 ft ft	E	e of e	oc 74
Puckett ''A'' ell No. <u>19</u> is loca	ted1345_ ft. from	N] Sy line and _1345 ft. fr	$\operatorname{rom} \left\{ \begin{array}{c} \mathbf{E} \\ \mathbf{K} \end{array} \right\}$	e of s	ec. <u>24</u>
ell No. 19 is loca	ť		rom E lin	e of s	ec. <u>24</u>
Puckett "A" ell No. <u>19</u> is loca <u>3W NE Sec. 24</u> (4 Bec. and Bec. No.)	ť	IE NAPM	rom <mark>{E }</mark> lin	e of s	ec. <u>24</u>
ell No. <u>19</u> is loca 3W NE Sec. 24	173 3 (Twp.) (Rar	1E NM PM nge) (Meridian)			

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

It has been established through packer tests that communication exists between perforations at 3548-58 and perforations at 3694-3702 behind the $5\frac{1}{2}$ " casing. It is proposed to repair this by setting a bridge plug at 3610' and squaezing 75 sacks below a retrievable retainer set at about 3450'. This is a water injection well.

REC - 1 1 1 1 1

MAR 4 CB64

O. C. C.

ARTESIA, OFFICE I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Address 302 Carper Building

Artesia, New Mexico

By Raych Z

Title Consulting Engineer.