

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		5. LEASE DESIGNATION AND SERIAL NO. LC-029418(b)
2. NAME OF OPERATOR Skelly Oil Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P. O. Box 1351, Midland, Texas 79701		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' FSL and 1980' FEL, Sec. 26-17S-31E		8. FARM OR LEASE NAME Lee "D"
14. PERMIT NO. R-3952		9. WELL NO. 6
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3837' DF		10. FIELD AND POOL, OR WELDCAT Grayburg-Jackson
		11. SEC., T., R. M. OR BLK. AND SURVEY OR AREA Sec. 26-17S-31E
		12. COUNTY OR PARISH 13. STATE El Paso New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) ☐	

(Other) **Convert to water injection**

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

This well has been producing from open hole section 3850-3981'. We propose the following work which has been approved under Order No. R-3952.

- 1) Move in and rig up completion unit.
- 2) Pull rods, lower tubing to check for fill, clean out if necessary.
- 3) Wash hole with 500 gallons acid.
- 4) Run 2-3/8" OD coated injection tubing with 5-1/2" internally coated tension type packer and equip to inject. Set packer at approximately 3800'.
- 5) Load casing annulus with inhibited fluid.
- 6) Hook well to injection system and begin injection.

This will be a water injection well for the Lee "D" lease operated by Skelly Oil Company.

RECEIVED

JUN 8 1970

O. C. C.
ARTESIA, OFFICE

RECEIVED
JUN-5 1970
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED (Signed) <u>J. R. Arent</u>	TITLE <u>Dist. Admintr. Coordinator</u>	DATE <u>June 2, 1970</u>
(This space for Federal or State office use)		

APPROVED
JUN - 5 1970
R. L. BEEKMAN
ACTING DISTRICT ENGINEER

TITLE _____ DATE _____

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State office. In addition, such proposals and reports should include reasons for the abandonment; data already formed or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; kind of other material placed below, between and above plugs; amount, size, and method of parting of any casing, inner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking for approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1965 O-685229

RECEIVED
JUN - 2 1965
U.S. GEOLOGICAL SURVEY

RECEIVED

GUIDE BY NOTICES AND REPORTS ON WELLS

GEOLOGICAL SURVEY

DEPARTMENT OF THE INTERIOR

UNITED STATES