January 11, 1961

Ashman and Hilliard, No. 3 Ltd. 1605 Wilco Building Midland, Texas

> Re: 32 Simon State No. 1, Unit No. H, Sec. 32-175-31E, Eddy County, New Mexico

ł.

Gentlemon:

An inspection of the site of the above-captioned well on January 7, 1961, reveals that the pit has not been filled and the "dead-man" wires not cut. This work must be done before form C-103 (Flugging Report) can be approved.

Please inform this office as soon as the above work has been completed so that we may make final inspection and approve the plugging reports for this well.

Very truly yours,

OIL CONSERVATION COMMISSION

WAG/sa

W. A. Gressett Oil & Gas Inspector francos II., 1965

Alexan and Willford, Lo. & Lo. . 1605 - Miso Buliding Midlend, **Taxas**

ແນະ (4) S.L.ແນ ລຽລຮະບ ໄດ. ໄ. ນີລະນີ ທີ່ດະ ທີ່, Soc. ທີ່ກະມີໃຫ້ ທີ່ມີ, ລີດຖະບົກຫອ້າງ, ທີ່ອນ ໂຮນໂທດ

ಶ್ ಕ್ರಿ ೇಶನೇ

is imprection of the site of the approximation will on functory 7, 1901, reveals the pit has not been filled and the Real-math stree not mut. This took must be cone solve for the Screaker Topset and be approved.

Rassi hefore this office of a or as the store which is been orepleted so that to may make final increation and sparous the plugging reports for this well.

generation for the state

WITERLAID WITTAKE FURDION

 $(\mathbf{x}_{i})_{i\in I}$

NAG/Se.

C. A. Crazzott ML & Ges Discustor