

8-1-79

B-32-17-31 Arco oil + Gas New Mexico *U#1

Ran Bond Log Top Cement @ 1635

Perforated @ 1600 @ Tried to Circulate Could NOT

Retainer @ 1548 ~~Squeezed~~ Squeezed with 135 SX salt saturated 2% CC Pumped 105
SX in Formation ~~Dumped~~ Hole in CSG Stopped Mixing and
Dumped Cement on Retainer

8-2-79

Went in Hole with Tubing Tagged Cement @ 1365

Tested Squeeze Job to 1000 PSI OK, Ran Temperature
Survey Could not Tell anything about the Cement
Because they Circulated Hole with Gel HA! HA!

Perforated @ 700 Broke Circulation @ Cemented with
150 SX Set Retainer @ ~~1548~~ 654 and Circulated
Cement

By BW