of contra acces	VED 3				投 扩 疗	7 31 50 00				
40. OF COPIES RECEI					1 % Sheet Gard	VED	Form C-103 Supersedes (Old		
DISTRIBUTION							C-102 and C-			
SANTA FE		NI	EM WEXICO OIL	_ CONSE	ERVATION	ission 970	Effective 1-1	-65		
FILE					138° 14 16.	~ ~ (3)1)			_	
U.S.G.S.							5a. Indicate Typ	e of Lease		
LAND OFFICE					1	L. L.	State X	Fee		
OPERATOR						GFFICE	5, State Oil & G	as Lease No.	_	
							647			
	SLIN	VDRY NOTICES	AND REPOR	TS ON 1	WELLS		THITTE		7	
(DO NOT USE T	HIS FORM FOR	NDRY NOTICES R PROPOSALS TO CRIL LICATION FOR PERMIT	L OR TO DEEPEN OF	R PLUG BA	CK TO A DIFFERENT !	RESERVOIR.			7	
1.	332 2772	TOATTON TON TENANT	_ (FORM C=101)	FOR SOCH	PROPOSALS.)		7. Unit Agreeme	nt Name	~	
OIL XX	GAS WELL	OTHER-								
2. Name of Operator		OTRER-		·			8. Farm or Leas	e None	_	
AMERICAN PETROFINA COMPANY OF TEXAS								Welch Duke State		
		MA COMPANI C	JE TEARS			<u>-</u>	9. Well No.	uke State		
3. Address of Operator			70720				1			
Box 1311, Big Spring, Texas 79720							17			
4. Location of Well								10. Field and Pool, or Willicat		
UNIT LETTERE		1820 FEE	T FROM THE NO	rth	LINE AND 820	FEET FROM	Artesia			
									7,	
- West		ECT104 28		189	22	8F			/	
THE WEST	LINE, S	EST164	TOWNSHIP	1.00	RANGE	OLL NMPM.			Ί,	
mmm	777777	MM7777	Flevation (Show)	whether I	F, RT, GR, etc.		12. County	. 7444444	7,	
							1		/	
$\frac{1}{1}$	777777	7111111					l Eddy	_(1111111111111111111111111111111111111	7	
10.	Che	ck Appropriate	Box To India	cate Na	ture of Notice	, Report or Otl	aer Data			
N	OTICE OF	F INTENTION T	го:	1		SUBSEQUENT	REPORT OF:	•		
PERFORM REMEDIAL WO	RK		PLUG AND ABANDO	CN	REMEDIAL WORK		ALTER	RING CASING	7	
TEMPORARILY ABANDON	\Box				COMMENCE DRILLING	OPNS.	PLUG	AND ABANDONMENT XX	ă	
PULL OR ALTER CASING	H		CHANGE PLANS		CASING TEST AND CE	 - 		<u> </u>		
TOTAL ON PLANT CONTINUE					OTHER _			[۲	
07.115.0					OTHER				۲	
OTHER	-			— L—i [
17. Describe Proposed	or Complete	ei Orecutions (Clear	lv state all pertir		ls, and give pertine	nt dates, including	estimated date of	starting any propose	\overline{d}	
work) SEE RULE	1103.	•					ŕ	J ,		
10/5/50	_					0.00051				
10/5/70	10/5/70 Spotted 2 Sx mud and 50 Sx cement down tubing @ 2035									
dispacing fluid										
Shot 5-1/2" casing @ 1394 and 1224. Spotted 3 Sx mud and 25Sx cement								nt		
	@ 1220 down casing. Pulled casing to 630.									
	Spotted 3 Sx mud and 25 Sx cement @ 630 down casing. Recovered 1224									
	of 5-1/2" casing.									
Set 4-1/2" marker and 10 Sx cement @ surface.										
		als between								
	11100111		P							
12/5/70	Locatio	on clean and	roady for	incn	ation					
12/3/10	Locatio	on cream and	. ready 101	rnspe	ection.					
<i>~</i> 1										
18. I hereby certify tha	t the informa	ition above is true a	and complete to th	e best of	my knowledge and	belief.			_	
	1		-							
1/2-	// (₁ /	(a	(D = = = :	• •	n na an	·	10/1	10/70		
SIGNED 1	<u> </u>	J.M	L. Denson TITL	ε Asst	. District	agr, or Proc	1. DATE 14/	LU/ / U	_	
								4 4		
· · · · · · · · · · · · · · · · · · ·					OJI AND GAS IN	SPECTOR	JAN.	1 4 1971		

CONDITIONS OF APPROVAL, IF ANY: