

NO. OF COPIES RECEIVED	
DISTRIBUTION	3
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

RECEIVED
NEW MEXICO OIL CONSERVATION COMMISSION

JUL 27 1970

O. C. C.
ARTESIA, OFFICE

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

<p align="center">SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" FORM C-101) FOR SUCH PROPOSALS.)</p>		5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Injection Well		5. State Oil & Gas Lease No ***
2. Name of Operator AMERICAN PETROFINA COMPANY OF TEXAS		7. Unit Agreement Name ***
3. Address of Operator Box 1311, Big Spring, Texas 79720		8. Farm or Lease Name Welch Duke State
4. Location of Well UNIT LETTER <u>E</u> , 1658 FEET FROM THE North LINE AND 269 FEET FROM THE West LINE, SECTION 28 TOWNSHIP 18S RANGE 28E NMPM.		9. Well No. 13
15. Elevation (Show whether DF, RT, GR, etc.) 3562 GR		10. Field and Pool, or Wildcat Artesia
12. County Eddy		

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Approximately - August 11, 1970

**Run 2" tubing to TD (2018') and spot 50 sx cement plug using mud laden fluid as displacing medium.
Place 10 sx cement plug in top of 4-1/2" casing and set 4" pipe marker.**

JCC/js

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Cliff Chapman **Cliff Chapman** TITLE Petroleum Engineer DATE July 24, 1970

APPROVED BY W. A. Gressett TITLE OIL AND GAS INSPECTOR DATE JUL 26 1970

CONDITIONS OF APPROVAL, IF ANY: