

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IT
(Other side
reverse side)

IPPLICATE
ON OR RE

Form approved.
Budget Bureau No. 42
5. LEASE DESIGNATION AND SERIAL

058126

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. NAME OF OPERATOR Ernest A. Hanson
3. ADDRESS OF OPERATOR P. O. Box 1515, Roswell, New Mexico
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 990' FNL & 1980' FEL Sec. 19, T-18-S, R-29-E, N.M.P.M. Eddy County, New Mexico
14. PERMIT NO.
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3571' DF

7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME Yates Federal
9. WELL NO. 1
10. FIELD AND POOL, OR WILDCAT Loco Hills
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 19 - 18S - 29E
12. COUNTY OR PARISH Eddy
13. STATE N. Mex.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETE	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON*	<input checked="" type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
(Other)			

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
FRACTURE TREATMENT	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
SHOOTING OR ACIDIZING	<input type="checkbox"/>	ABANDONMENT*	<input type="checkbox"/>
(Other)			

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

T.D. @ 2461' Perfs. @ 2378-2426'
5-1/2" @ 2460' w/100 sx.

It is proposed to plug and abandon the captioned well in the following manner:

1. Displace hole with heavy mud.
2. Spot 20 sx. cmt. plug @ 2289-2460' across perfs.
3. Back-off & recover as much 5-1/2" csg. as possible.
4. Spot 20 sx. cmt. plug in-and-out of 5-1/2" casing stub.
5. Spot 20 sx. cmt. plug @ 0-28' in top of hole.
6. Erect a regulation dry hole marker.
7. Clean-up location for final inspection by U.S.G.S.

RECEIVED

1967

RECEIVED
OCT 23 1967
U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED Harry J. Schuman TITLE Exploration Manager DATE 10-20-67

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side