(May 1963)		N. M. C.	SUBMIT IN ARIP.	E* Form approved. Budget Bureau No. 42-R1424.
		F THE INTERIC	(Other Instructions 52 -	5. LEASE DESIGNATION AND SERIAL NO. NM-033775
SUN (Do not use this	IDRY NOTICES AN form for proposals to drill of Use "APPLICATION FOR H	ID REPORTS O	N WELLS	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
1.			RECEIVE	D 7. UNIT AGREEMENT NAME
OIL GAS WELL WELL 2. NAME OF OPERATOR	L OTHER Injec	ction Well	MAY 2 0 1975	North Benson Queen Un 8. FARM OR LEASE NAME
TEXACO Inc	•		0 107 0	
3. ADDRESS CF OPERATOR	* 728, Hobbs, Nev	y Movieo S	O.C.C.	9. WELL NO.
	Report location clearly and in		824RTESIA, DEFICE	10, FIELD AXD FOOL, OF WILDCAT NOT TH BENSON
	& ббО <b>'</b> FEL of S r "H"	Sec. 28, T-1	8-S, R-30-E	Queen Grayburg 11. sec., t., e., m., or blk. And SURVEY OR AREA
14. PERMIT NO.	15. ELEVAT	10NS (Show whether DF. J	T. GR. etc.)	Sec. 28, T-18-S, R-30- 12. COUNTY OF PARISH 13. STATE
Regular		3481 DF		Eddy N.M.
16.	Check Appropriate	Box To Indicate Nc	ture of Notice, Report, o	r Other Data
1	NOTICE OF INTENTION TO:		SUBS	SEQUENT REPORT OF:
TEST WATER SHUT-O			WATER SHUT-OFF	REPAIRING WELL
FRACTUBE TREAT Shoot or acidize	ABANDON*	MPLETE	FRACTURE TEEATMENT SHOOTING OR ACIDIZING	X ABANDONMENT*
REPAIR WELL	CHANGE PLAN	s	(Other)	alts of multiple completion on Well
2. Pld tbg	& pkr. Prep t	o run RBP &	pkr & acidize.	
<ol> <li>Howco ac w/10% Mu</li> <li>Ran 4<sup>1</sup>/<sub>2</sub>" to inj.</li> <li>Displace 500# OK.</li> </ol>	pkr on PC tbg d tbg csg annu	Morflo. set at 2691 llus w/ inhil	1500 gal. 15% N . Prep to test oited wtr. Tes	EA csng & retr ted csng to
<ol> <li>Howco ac w/10% Mu</li> <li>Ran 4½" to inj.</li> <li>Displace 500# OK.</li> <li>Inj. 750</li> </ol>	pkr on PC tbg d tbg csg annu	Morflo. set at 2691 llus w/ inhil into Queen	1500 gal. 15% N . Prep to test bited wtr. Tes perf 2754'-331	EA csng & retr ted csng to l'.
<ol> <li>Howco ac w/10% Mu</li> <li>Ran 4½" to inj.</li> <li>Displace 500# OK.</li> <li>Inj. 750 Return t</li> </ol>	asol & 5 gals. pkr on PC tbg ed tbg csg annu ) BWPD at 1650# to Inj. 5-14-75	Morflo. set at 2691 lus w/ inhi into Queen	1500 gal. 15% N . Prep to test bited wtr. Tes perf 2754'-331	EA csng & retr ted csng to 1'. RECEIVED MAY 16 10
<ol> <li>Howco ac w/10% Mu</li> <li>Ran 4½" to inj.</li> <li>Displace 500# OK.</li> <li>Inj. 750 Return t</li> </ol>	the foregoing is true and co	Morflo. set at 2691 llus w/ inhib into Queen	1500 gal. 15% N . Prep to test bited wtr. Tes perf 2754'-331 4	TEA csng & retr ted csng to 1'. RECEIVED MAY 16 1975 RTESIA, NEW MEXICO
<ul> <li>Howco ac w/10% Mu</li> <li>Ran 4½" to inj.</li> <li>Displace 500# OK.</li> <li>Inj. 750 Return t</li> </ul>	asol & 5 gals. pkr on PC tbg ed tbg csg annu ) BWPD at 1650# to Inj. 5-14-75	Morflo. set at 2691 lus w/ inhib into Queen	1500 gal. 15% N . Prep to test bited wtr. Tes perf 2754'-331	TEA csng & retr ted csng to 1'. RECEIVED MAY 16 1975 RTESIA, NEW MEXICO
<ol> <li>Howco ac w/10% Mu</li> <li>Ran 4½" to inj.</li> <li>Displace 500# OK.</li> <li>Inj. 750 Return t</li> </ol>	the foregoing is true and co	Morflo. set at 2691 llus w/ inhib into Queen	1500 gal. 15% N . Prep to test bited wtr. Tes perf 2754'-331 4	TEA csng & retr ted csng to 1'. RECEIVED MAY 16 1975 RTESIA, NEW MEXICO