

U. S. O. C. C. COPY
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Copy J. F.
to
SUBMIT IN
(Other inst.
verse side)

IPPLICATE*
ions on re-

Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.
Saunders B, LC050422-B
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Dixon & Yates Oil Company		8. FARM OR LEASE NAME Saunders "B"
3. ADDRESS OF OPERATOR 323 Carper Building, Artesia, New Mexico.		9. WELL NO. 2-B
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 990/S & 2310/- line, sec. 12, T. 18 S., R. 29 E., N.M.P.M.		10. FIELD AND POOL, OR WILDCAT Loco Hills
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Unit B, Sec. 12, T. 18 S., R. 29 E.
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 5504, Ground Level.		12. COUNTY OR PARISH Eddy
		13. STATE N. Mex.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☒	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐
REPAIR WELL ☐	CHANGE PLANS ☐
(Other) Open hole, run casing. ☒	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
(Other) ☐	
(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Confirming our telephone conversation of today, plan to check total depth with sand pump and depth meter, to ascertain if there is fill up to be removed.

Then plan to run approximately 2650' of 4 1/2", 9.50#, J55 CF & I Casing, equipped with Howco Full Flow Packer Shoe, and cement with 100 sacks of Lone Star Neat Cement. Plan to set packer and cement with ports open at 300#, close ports and pump off nose at 600#. Then confirm open hole with wire line measurement.

RECEIVED

OCT 16 1964

O. C. C.
ARTESIA. OFFICE

18. I hereby certify that the foregoing is true and correct

SIGNED *R. L. Moore* TITLE Superintendent. DATE Oct. 12, 1964
(This space for Federal or State office use)

APPROVED BY *R. L. Moore* TITLE Superintendent. DATE Oct. 12, 1964
CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.