

GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back. Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> WTW		MAR 25 1983	
2. NAME OF OPERATOR Newmont Oil Company		O. C. D.	
3. ADDRESS OF OPERATOR P. O. Box 1305 Artesia, N.M.		ARTESIA, OFFICE 88210	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 990' FSL 2310' FWL Sec. 12-18S-R29E			
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3504'		16. COUNTY OR PARISH Eddy
17. STATE N.M.		18. UNIT AGREEMENT NAME West Loco Hills Grb #4 SD	
19. FARM OR LEASE NAME Tract 4		20. WELL NO. 2	
21. FIELD AND POOL, OR WILDCAT Loco Hills (O.G. SA)		22. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 12-18S-29E	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐PULL OR ALTER CASING ☐WATER SHUT-OFF ☐REPAIRING WELL ☐FRACTURE TREAT ☐MULTIPLE COMPLETE ☐FRACTURE TREATMENT ☐ALTERING CASING ☐SHOOT OR ACIDIZE ☐ABANDON* ☐SHOOTING OR ACIDIZING ☐ABANDONMENT* ☒REPAIR WELL ☐CHANGE PLANS ☐(Other) ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plugged and abandoned well as follows....


1/18/83....Set CIBP @ 2542'.

1/19/83....Spotted 25 sacks on top of bridge plug. Perf 4 shots @ 1027'. Squeezed 50 sack into perms @ 300 psi

1/20/83....Pressured plug to 1000 psi. Tagged plug with wireline @ 770'. Perf. 4 shots @ 400'. Bullhead squeezed 50 sacks.

1/22/83...Tagged plug @ 135' with wireline. Pumped 60 sacks, circulated to pit, Set P&A marker

Location ready for inspections



OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Area Manager

DATE

3/8/83

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

Post ID-2
4-1-83
P+R