

NO. OF COPIES RECEIVED	5
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

RECEIVED
NEW MEXICO OIL CONSERVATION COMMISSION

JUN 1 1971

O. C. C.
ARTESIA, OFFICE

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-7866

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Sun Oil Company	8. Farm or Lease Name South Hope Unit
3. Address of Operator P. O. Box 1861 Midland, Texas 79701	9. Well No. 2
4. Location of Well UNIT LETTER <u>A</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>810</u> FEET FROM THE <u>East</u> LINE, SECTION <u>36</u> TOWNSHIP <u>18 S</u> RANGE <u>21 E</u> NMPM.	10. Field and Pool, or Wildcat South Hope Penn.
15. Elevation (Show whether DF, RT, GR, etc.) 4132 DF	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Casing Pullers: C. E. Knight & Co., Box 86, Snyder, Texas

5-20-71 Load hole with 9.5# mud. Squeezed perfs 7277-7297 with 25 sks cement below packer set @ 7250, TOC 7160.
5-21-71 Shot 4 1/2" casing @ 4491, pull & lay down 144 joints.
5-24-71 Spot 35 sk cement plugs as follows: 4398-4498, 3400-3500, 1742-1842, 546-646.
5-25-71 Spot 10 ft. cement plug at surface. Set marker and clear location.
Pipe left in hole:
13 3/8" - 120'
8 5/8" - 1792'
4 1/2" - 2964'

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED RW Hughes TITLE Proration Clerk DATE May 28, 1971

APPROVED BY O. L. Howe TITLE OIL AND GAS REG. CTOR DATE JUN 4 1971

CONDITIONS OF APPROVAL, IF ANY: