NE MEXICO OIL CONSERVATION COM...ISSION For Comp. C-104) Santa Fe, New Mexico

REQUEST FOR (OIL) - (GAS) ALLOWABLE AND A TONIO WELL AND AND ALLOWABLE AND A TONIO WELL AND

This form shall be submitted by the operator before an initial allowable will be assigned to any completed Oil or Gas well. Form C-104 is to be submitted in QUADRUPLICATE to the same District Office to which Form C-104 was sent. The allowable will be assigned effective 7:00 A.M. on date of completion or recompletion, provided this form is filed during calendar month of completion or recompletion. The completion date shall be that date in the case of an oil well when new oil is delivered into the stock tanks. Gas must be reported on 15.025 psia at 60° Fahrenheit.

E ARE H	EREBY R	EQUESTI	NG AN ALLOWABLE FOR	(Place) A WELL KNOV	VN AS:		(Date)
			ON Me Care F				
C	mpany or Op	erator) 19	(Lease) , T 18 S. , R 25 E.	NMPM und	Loco Hills		Pool
Unit Let	ter						
E	ddy		County. Date Spudded7-	29-63	Date Drilling	capleted	8-21-63
Please indicate location:		ocation:	Elevation 3554' DF				
D	СВ	A	Top Oil/Gas Pay 23581	Name of N	Prod. Form.	stayburg.	
~ `		-	PRODUCING INTERVAL -				
	<u> </u>		Perforations liet @ 2358	,2359,2340,23	99,2400,24	01,2402,2	2406]
E	F G	H	Open Hole	Depth Casing Sl	noe 2432'	Tubing_	
			OIL WELL TEST -				
L	K J	I	Natural Prod. Test: 181 90	land and	bble water is	n 1 hre	Choke
]				
v	N O	P	Test After Acid or Fracture				Choke
M	" 0	•	load oil used): 43 bbl	s,oil, <u>0</u> b	bls water in 24	hrs,	min.Size
			GAS WELL TEST -				
0' FNL & 2040' FWL			Natural Prod. Test:	MCF/Day;	Hours flowed _	Choke	Size
	ing and Cem			ck pressure, etc.)	:		·
Size	Feet	Sax	Test After Acid or Fracture				
- 6	200		Choke Size Method o				
-5/8	320	Pulled					
-1/2	2432	100	Acid or Fracture Treatment (
			sand): 40,000 gals. lee	se oil and 30,	000 sand	<u> </u>	
		į	Casing Tubing Press. Press.	Date first ne	w nks <u>8-26-63</u>	<u></u>	
	 	 	Oil Transporter McWo				
		_	Gas Transporter Philli	•			
	h 1111 9-4	4lau	will be contacted for the g			ion of the	·· boah
D		TATOR WARTINES	XIII BE CHIECIES IN THE	es vernieunen i	Spent Cambie.	ION OF THE	IUIN
.emarks : P.	AUUPS.ES		arabas inchallation		• •		
emarks : P.	attery and	a gas sepa	arator installation.				••••••
Ь	attery and						
Ь	by certify t	hat the infe	formation given above is true a	ınd complete to th	e best of my kr	owledge.	
b	by certify t	hat the infe			e best of my kr	owledge.	
I here	by certify t	hat the info	formation given above is true a	ınd complete to th	e best of my kn T.A. HANS (Company or	owledge. ON Operator)	
I here	by certify t	hat the info	formation given above is true a	ınd complete to th	e best of my kr	owledge. ON Operator)	
I here	by certify t	hat the info	formation given above is true a	By Age	e best of my kr. T.A. HANS (Company or (Signat	owledge. Operator)	
I here	by certify t	hat the info	formation given above is true a	By Age	e best of my kn T.A. HANS (Company or (Signate	owledge. Operator)	well to:
I here	by certify t	hat the info	formation given above is true a	By Age	e best of my kr. T.A. HANS (Company or (Signate or communication)	Operator) Operator) ure)	well to: