

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN  
(Other inst. on re-  
verse side)

PLICATE\*

Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-063621-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Mastellar A

9. WELL NO.

1-A

10. FIELD AND POOL, OR WILDCAT

Loco Hills

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 7-18S-30E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

TOM BOYD, ET AL

3. ADDRESS OF OPERATOR

510 West Texas St., Artesia, New Mexico 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)

At surface

2310' from North and East Lines of Sec. 7-18S-30E.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3517 (Gr.)

16.

## Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

## SUBSEQUENT REPORT OF:

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

Total depth is 2823', 5½" 15.5# J-55 casing is cemented at 2799' with 100 sacks. 3-5/8" 24# casing is cemented at 432' with 75 sacks. Top of salt is at 408', Base of salt is at 1140'.

It is proposed to plug and abandon this well as follows:

Set cement retainer in 5½" between 2750' and 2775', and squeeze below with 25 sacks of cement.

Out and pull an estimated 1,000 feet of 5½" casing. Place a cement plug from 50' above 5½" stub to 50' below 5½" stub. Place a cement plug from 482' back to 382'. Place a 20" cement plug in top of hole. Place 4" marker with suitable markings.

Verbal approval to proceed with work was obtained from Mr. Beckman on December 27, 1967.

18. I hereby certify that the foregoing is true and correct

SIGNED

Ray L. Beckman

TITLE

Consultant

DATE Dec. 27, 1967

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

APPROVED

R. L. BECKMAN

REGISTERED PROFESSIONAL ENGINEER

RECEIVED  
DEC 27 1967  
U. S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

\*See Instructions on Reverse Side