

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN
(Other instr
verse side)

ICATE*

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

New Mexico - 0924

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal Sivilay Alcott

9. WELL NO.

5-30

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

S. 30, T18S, R29E, M27N

12. COUNTY OR PARISH

Eddy

13. STATE

N. M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL
WELL

☐

GAS
WELL

☐

OTHER

Temporarily Abandoned

2. NAME OF OPERATOR

John M. Trigg

3. ADDRESS OF OPERATOR

P. O. Box 106 - Maljamar, New Mexico

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)
At surface

660 Feet from North Line and 1913.2 Feet from West

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3532.4 Gr.

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☐
☒
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion or Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plugs set May 31, 1963 - 30 sx. 9390-9490
30 sx. 8470-8570
30 sx. 7100-7200
30 sx. 4800-4900
50 sx. 4400-4600

June 6-17, 1963 - Tested San Andres from 4230' to 4260' with Lynes straddle
Packers. Acidized w/5500 gal. 15% HX acid. Shut tested approx.
20 MFPD + 10 MFPD after 10 days testing. Original bottom hole
pressure on DST was 1600 psi. Recorded 800 psi after 10 days test.
Decided to abandon. Cut & recovered 1922' of 8-5/8" OD Std. 244
casing. Temporarily abandoned on June 22, 1963.

We propose to plug and abandon this well in the following manner:

1. Fill hole with good mud.
2. Set 30 sx. plug from 3700' to 3600'.
3. Set 30 sx. plug from 850' to 750'.
4. Set 30 sx. plug from 450' to 350'
5. Set 20 sx. plug from 20' to surface.
6. Erect regulation marker.

18. I hereby certify that the foregoing is true and correct

SIGNED

J. M. Trigg

TITLE

Production Clerk

DATE

August 27, 1964

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

RECEIVED

AUG 31 1964

O. C. C.
ARTESIA, OFFICE

AUG 28 1964
U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

APPROVED
AUG 28 1964
P. L. BELLMAN
ACTING DISTRICT ENGINEER

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.