

NO. OF COPIES RECEIVED	6
DISTRIBUTION	
SANTA FE	1
FILE	1-
U.S.G.S.	
LAND OFFICE	
OPERATOR	4

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
047

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Cima Capital, Inc. (N.S.L.)	8. Farm or Lease Name Welch State
3. Address of Operator Box 1343, Artesia, New Mexico	9. Well No. 4
4. Location of Well UNIT LETTER <u>JK</u> , <u>2390</u> FEET FROM THE <u>V</u> LINE AND <u>2390</u> FEET FROM THE <u>S</u> LINE, SECTION <u>17</u> TOWNSHIP <u>10S</u> RANGE <u>20E</u> NMPM.	10. Field and Pool, or Wildcat Artesia
15. Elevation (Show whether DF, RT, GR, etc.)	12. County Elddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input checked="" type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

On or about February 16, 1966, propose to temporarily abandon this oil well.
Intend to spot 25 sack plug at 2380 to 2247; and 25 sack plug 2110 to 2010 and 25 sack
plug 2000' to 1900'. Plan to pull no casing but to use above program to
properly confine fluids to their present zones.

RECEIVED

FEB 15 1966

O. C.
ARTESIA

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Engineer DATE 14 Feb. 1966

APPROVED BY [Signature] TITLE ARTESIA DATE FEB 15 1966

CONDITIONS OF APPROVAL, IF ANY: