## N. M. O. C. G. CORN Dept 1 1

Form 9-331 (May 1963)			re Budge 5. LEASE DESIG		
	SUNDRY NOTICES AND REPORTS ON WELL use this form for proposals to drill or to deepen or plug back to a difference use "APPLICATION FOR PERMIT—" for such proposals.)		6. IF INDIAN, A	ALLOTTEE OR TRIBE NAME	
1.	GAS		7. UNIT AGREE	MENT NAME	
	WELL OTHER WATER INJECTION		8. FARM OR LE	ASE NAME	
VILLIAM			Pucket		
3. ADDRESS OF OR			9. WELL NO.		
302 Car	per Building, Artgeia, New Mexico		29		
See also space	NELL (Report location clearly and in accordance with any State requirement 17 below.)	ents.*	مميد ا	POOL, OR WILDCAT	
At surface	1345' from North and 25' from East Lines		11. SEC., T., R.	, M., OR BLK. AND	
	Sec. 24-175-318		SURVEY	OR AREA	
			Sec. 2	24-178-31E	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)		12. COUNTY OF	R PARISH 13. STATE	
16.	Check Appropriate Box To Indicate Nature of No	tice Report o	or Other Data		
	NOTICE OF INTENTION TO:		SEQUENT REPORT OF	:	
		SHUT-OFF	REF	PAIRING WELL	
TEST WATER FRACTURE TR		RE TREATMENT		TERING CASING	
SHOOT OR ACI	DIDIZE ABANDON* SHOOTI	ING OR ACIDIZING	X ABA	ANDONMENT*	
REPAIR WELL	CHANGE PLANS (Other	Nows · Report res	sults of multiple con	npletion on Well	
(Other)	Ċ	ompletion or Rec	ompletion Report an	d Log form.)	
17. DESCRIBE PROP proposed we nent to this	POSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and work. If well is directionally drilled, give subsurface locations and meas work.)*	give pertinent di sured and true ve	ertical depths for all	markers and zones perti-	
On James	ry 20, 1965, acidised as follows:				
Peri	Corations 3703-11 with 1,000 gallons 15% ac	id with H-	-38. Broke	at 1800 pai.	
Tres	nted at 1600 to 1200 psi. at 1-3/4 bbl./min	l.			
Peri Tres	forations 3915-38 with 1,000 gallons 15% ac ated at 1800-1600 psi. at 1-3/4 bbl./min.	id with M-	-38. Broke	nt 3500 pai.	
	a b				
Recovered	d load fluid and put well on water injection	m,			
	RECEIVED				
	₽EB 2 1965				
	4 CD C				
	. C. C.				
	BRITERIA, ORFILIS				
		\$ <sup>7</sup>			
18. I hereby certi	ify that the foregoing is true and correct				
SIGNED 💢	alish L. Lacy de TITLE Consulting	ingineer	DATE:	Jan. 27, 1965	
			DAIN _		
(This space f	for Federal or State office use)  BY May he Close TITLE ACTING DISTR	RICT ENGINE	.C(s	ER 1 1965	
APPROVED I	BY TITLE TITLE TO THE SOF APPROVAL, IF ANY:		DATE	Eu	

## Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Rederal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment: data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1963—O-685229

867-851