

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	/
FILE	/ ✓
U.S.G.S.	
LAND OFFICE	
OPERATOR	/

RECEIVED
 NEW MEXICO OIL CONSERVATION COMMISSION
NOV 20 1969
O. C. C.
ARTESIA, OFFICE

Form C-103
 Supersedes Old
 C-102 and C-103
 Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
 USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name Atoka San Andres Unit
2. Name of Operator Kewanee Oil Company ✓		8. Farm or Lease Name Tract 24
3. Address of Operator P. O. Box 3786, Odessa, Texas 79760		9. Well No. 2
4. Location of Well UNIT LETTER J 2310 FEET FROM THE South LINE AND 2310 FEET FROM THE East LINE, SECTION 13 TOWNSHIP 18S RANGE 26E NMPM.		10. Field and Pool, or Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 3295' GR		12. County Eddy

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>		COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER Convert to Water Injection Well <input checked="" type="checkbox"/>		OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Pull rods and tubing, clean out to TD of 1908' and wash hole down with 250 gallons acid. Set tension packer at approximately 1620' on 2-3/8" O. D. tubing coated internally with plastic and load annulus with inhibited water. Start fresh water injection down tubing at rate of about 200 BPD. Injection will commence on or about 1-1-70.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u><i>E. J. Stussman</i></u>	TITLE <u>Division Superintendent</u>	DATE <u>11-18-69</u>
APPROVED BY <u><i>W. A. Gressett</i></u>	TITLE <u>OIL AND GAS INSPECTOR</u>	DATE <u>NOV 21 1969</u>
CONDITIONS OF APPROVAL, IF ANY:		