

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

New Mexico 030752

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Dry Hole		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR John H. Trigg		8. FARM OR LEASE NAME Sivley Jennings Federal	
3. ADDRESS OF OPERATOR P. O. Box 106 - Hallsburg, New Mexico		9. WELL NO. 5	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980 Feet from North and 1980 Feet from West Lines		10. FIELD AND POOL, OR WILDCAT Undesignated Joco Hills	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, OR, etc.) 3515.4 ERM	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 21, T18S, R29E
		12. COUNTY OR PARISH Eddy	13. STATE N. Mex.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDONMENT* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

November 8, 1965 - Set the following cement plugs;

1. Set 35 sack cement plug from 6622 to 6522.
2. Set 35 sack cement plug from 6537 to 6607.
3. Set 35 sack cement plug from 5036 to 5156.
4. Set 35 sack cement plug from 2885 to 2916.
5. Set 35 sack cement plug from 1962 to 2062.

November 13, 1965 - Ran 1817' of 4 1/2" OD Std. 9.52 J-55 casing. Set @ 1817' and cemented with 150 sx. regular neat cement. Plug down @ 11:00 a.m. 11-13-65. Perforated 1664-66, 1660-62, 1656-58, 1633-39, 1624-34 with 2 holes per foot. Acidized with 1500 gal. Mud Acid and 50 ball sealers. Seab load acid and formation water. Well produced water with some oil.

November 18, 1965 - Cut 4 1/2" casing at top of cement and pulled. Recovered 1480' of 4 1/2" casing.

November 19, 1965 - Finished plugging through tubing as follows;

1. Set 35 sack cement plug from 1285 to 1331.
2. Set 35 sack cement plug from 940 to 1030.
3. Set 10 sack cement surface plug from 0 to 25'.
4. Erected regulation marker & cleaned up location.

Location is now ready for final inspection.

18. I hereby certify that the foregoing is true and correct

SIGNED

Kenneth E. Aston

TITLE

Production Clerk

DATE November 26, 1965


(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE



*See Instructions on Reverse Side

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN THE
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

New Mexico 030732

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal Bivley Jennings

9. WELL NO.

5

10. FIELD AND POOL, OR WILDCAT

Undesignated Poco Hills

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 21, T18N, R29E

12. COUNTY OR PARISH

Eddy

13. STATE

N. Mex.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Dry Hole NOV 11 1965

2. NAME OF OPERATOR

John M. Trigg

O. C. C.

3. ADDRESS OF OPERATOR

ARTESIA, OFFICE

P. O. Box 106 - Maljamar, New Mexico

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface

1980 Feet from North Line & 1980 Feet from West Line

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3513.4 KIM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☒

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

At a total depth of 9234' kim, we propose to plug and abandon this well as discussed with Mr. R. L. Beckman on November 8, 1965. The following procedure will be followed;

1. Set 35 sack cement plug from 8125 to 8625'.
2. Set 35 sack cement plug from 6400 to 6700'.
3. Set 35 sack cement plug from 5050 to 5150'.
4. Set 35 sack cement plug from 2800 to 2900'.
5. Set 35 sack cement plug from 1950 to 2050'.
6. Set 35 sack cement plug from 950 to 1050'.
7. Set 10 sack cement plug from surface to 25'.
8. All voids to be filled with good mud.
9. Regulation marker will be erected and location cleaned up.

Proper notice will be given when the above operations are completed.

18. I hereby certify that the foregoing is true and correct

SIGNED

Kenneth E. Aston
Kenneth E. Aston

TITLE

Production Clerk

DATE

November 9, 1965


(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY



*See Instructions on Reverse Side

RECEIVED
NOV 10 1965
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.