MG. OF COPIES RECEIVED	3	
DISTRIBUTION		
SANTA FE	1	
FILE		1
U.S.G.S.		
LAND OFFICE		
OPERATOR	1	

RECEIVED

NEW MEXICO OIL CONSERVATION COMMISSION . . . 6 **1970** -

Form C-103 Supersedes Old C-102 and C-103 Effective 1-1-65

5a. Indicate Type of Lease

LAND OFFICE	Careal Series Series	State X Fee
OPERATOR	O. C. C.	5. State Oil & Gas Lease No.
GPERA! OR	ARTEGIA, OFFICE	E-5461
SUNDS	RY NOTICES AND REPORTS ON WELLS OPOSALS TO DELL OR TO DEEPEN OR PLUE BACK TO A DIFFERENT RESERVOIR. TION FOR PERMIT — (FORM C-101) FOR SUCH PROPOSALS.)	
1. OIL GAS WELL WELL	OTHER- P & A	7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name Hondo "C" State
Atlantic Rich	field Company	nondo C State
3: Address of Operator		9. Well No.
P. O. Box 1978	8, Roswell, New Mexico 88201	1
4. Location of Well		10. Field and Pool, or Wildcat
D	330 PEET FROM THE North LINE AND 990 FEET FRO	Empire
	TOWNSHIP 18-S RANGE 27-E NMPN	
	15. Elevation (Show whether DF, RT, GR, etc.) 3616 DF	12. County Eddy
16. Check	Appropriate Box To Indicate Nature of Notice, Report or O	ther Data
	• • •	IT REPORT OF:
PERFORM REMEDIAL WORK	PEUS AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS.	ALTERING CASING PLUG AND ABANDONMENT

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well has now been plugged and abandoned in the following manner:

Shot off 7" casing @ 1734'. Pulled 53 jts 7" casing. Spotted 160 sk Class "A" cmt plug 1304-1765'. Spotted 40 sk Class "A" cement plug 860-960' (across 8-5/8" shoe). Perforated 8-5/8" casing 549-550 w/four 1/2" JS. Well went on strong vacuum. Cemented these perfs w/100 sx Class "A" cement. Displaced cement to 449' using top rubber plug. No returns to surface. Set 10 sk cement plug in top of well. dry hole marker. Well P & A 6/29/70.

11 Katalia	Dist Drlg. Supervisor	7/1/70	
ICHED WYNTERES	TITLE		
PPROVED BY TY & Clamb	TITLE	DATE	