

Page 2: History

MY III - Atoka State No. 4 16-18S-26E

8-25-26-27-28 - SD on account of weather.

8-29-66 - Cleaning up location and preparing to plug and abandon.
well in the following manner. 735-800' 25 sacks of
cement. 590-680' 35 sacks of cement and 200-250'
25 sacks of cement. Set well marker and clean up location
for inspection.

8-30-31-66 - Set well marker and cleaned up location. Well
Plugged and Abandoned. Final Report