•	DEFAR	TMEIL OF THE INT	-	5. LEASE DESIGNATION AND BERIAL NO.
SUNDRY NOTICES AND REPORTS ON WELLS				6. IF INDIAN, ALLOTTEE OR TRIBE NAME
(Do not use	this form for pro Use "APPL:	posals to drill or to deepen or pl ICATION FOR PERMIT—" for su	ug back to a different reservoir. ch proposals.)	
1. 01L YY GAS	s (7. UNIT AGREEMENT NAME
WELL WE				W. LOCO Hills G. 48. Ut
Newmont 0il Company 2				Tract 198
3. ADDRESS OF OPER P		Artesia, New Mexico	88210	9. WELL NO.
	L (Report location	a clearly and in accordance with		10. FIELD AND POOL, OB WILDCAT
At surface			1070	Loco Hills
1650	FNL & 990	FEL of Section 9	JUN 5 1973	11. SEC., T., R., M., OR BLK, AND BUBYEY OR AREA
				Sec. 9-185-29E - NMPM
14. FERMIT NO.		15. ELEVATIONS (Show wheth		12. COUNTY OR PARISH 13. STATE
16.	<u> </u>		3501 G.L.	Eddy New Mexi
~ ~	Check /		e Nature of Notice, Report, o	이 이 이 이 이 이 이 이 이 이 이 이 이 이 이 이 이 이 이
	LJ	г		SEQUENT REPORT OF:
TEST WATER SH FRACTURE TREAT		PULL OR ALTER CASING	WATER SHUT-OFF Fracture treatment	XX ALTERING CASING
SHOOT OR ACIDIZ		ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT
REPAIR WELL		CHANGE PLANS	(Other)	
(Other)			Completion or Rec	ompletion Report and Log form.)
proposed work nent to this wo	. If well is dire	ctionally drilled, give subsurface	locations and measured and true ve	ates, including estimated date of starting an ertical depths for all markers and zones pert
5-17-73Pert 30 -	orated Zish 7/80 ball	sealers followed w	494' - 2504'. Pumped	1000 gals 15% acid with
30 -	7/8" ball	sealers, followed w	ith 110 gals Tretoli	te gyp chemical in 20
30 - barr cont	7/8" ball els of wate aining 2 P	sealers, followed w er, followed with 19 PG 20/40 sand, follo	vith 110 gals Tretoli 500 gals X-E frac pad owed with 5000 gals co	te gyp chemical in 20 , followed with 2500 gals ontaining 3 PPG 20/40
30 - barr cont sand	7/8" ball els of wate aining 2 P , followed	sealers, followed w er, followed with 19 PG 20/40 sand, follo with 5000 gals cont	with 110 gals Tretoli 500 gals X-E frac pad owed with 5000 gals co caining 4 PPG 20/40 so	te gyp chemical in 20 , followed with 2500 gals ontaining 3 PPG 20/40 and, flushed with oils.
30 - barr cont sand Shut	7/8" ball els of wate aining 2 P , followed	sealers, followed w er, followed with 19 PG 20/40 sand, follo with 5000 gals cont ght. ISDP 1400 psi.	with 110 gals Tretoli 500 gals X-E frac pad owed with 5000 gals co caining 4 PPG 20/40 so	te gyp chemical in 20 , followed with 2500 gals ontaining 3 PPG 20/40 and, flushed with oils.
30 - barr cont sand Shut pump	7/8" ball els of wate aining 2 P , followed in overnie ing rate 20	sealers, followed w er, followed with 19 PG 20/40 sand, follo with 5000 gals cont ght. ISDP 1400 psid D BPM.	with 110 gals Tretoli 500 gals X-E frac pad owed with 5000 gals co caining 4 PPG 20/40 so	te gyp chemical in 20 , followed with 2500 gals ontaining 3 PPG 20/40 and, flushed with oils.
30 - barr cont sand Shut	7/8" ball els of wate aining 2 P , followed in overnie ing rate 20	sealers, followed w er, followed with 19 PG 20/40 sand, follo with 5000 gals cont ght. ISDP 1400 psid D BPM.	with 110 gals Tretoli 500 gals X-E frac pad owed with 5000 gals co caining 4 PPG 20/40 so	te gyp chemical in 20 , followed with 2500 gals ontaining 3 PPG 20/40 and, flushed with oil ressure 2200 ps, average
30 - barr cont sand Shut pump •22-73Reco	7/8" ball els of wate aining 2 P , followed in overnig ing rate 20 vered all	sealers, followed w er, followed with 19 PG 20/40 sand, follo with 5000 gals cont ght. ISDP 1400 psi. D BPM. load oil.	vith 110 gals Tretoli 500 gals X-E frac pad 50wed with 5000 gals co aining 4 PPG 20/40 so Maximum treating p	te gyp chemical in 20 , followed with 2500 gals ontaining 3 PPG 20/40 and, flushed with oil ressure 2200 ps, average
30 - barr cont sand Shut pump •22-73Reco	7/8" ball els of wate aining 2 P , followed in overnig ing rate 20 vered all	sealers, followed w er, followed with 19 PG 20/40 sand, follo with 5000 gals cont ght. ISDP 1400 psid D BPM.	vith 110 gals Tretoli 500 gals X-E frac pad 50wed with 5000 gals co aining 4 PPG 20/40 so Maximum treating p	te gyp chemical in 20 , followed with 2500 gals ontaining 3 PPG 20/40 and, flushed with oil, ressure 2200 psi, averago AMAY 291973 MAY 291973
30 - barr cont sand Shut pump •22-73Reco	7/8" ball els of wate aining 2 P , followed in overnig ing rate 20 overed all r to treate	sealers, followed w er, followed with 19 PG 20/40 sand, follo with 5000 gals cont ght. ISDP 1400 psi. D BPM. load oil. ment30 bbls oi	ith 110 gals Tretoli 500 gals X-E frac pad owed with 5000 gals co aining 4 PPG 20/40 so Maximum treating p 1, 360 bbls water.	te gyp chemical in 20 , followed with 2500 gals ontaining 3 PPG 20/40 and, flushed with oil ressure 2200 ps , averago NAY 291973 NAY 291973 SUK
30 - barr cont sand Shut pump •22-73Reco	7/8" ball els of wate aining 2 P , followed in overnig ing rate 20 overed all r to treate	sealers, followed w er, followed with 19 PG 20/40 sand, follo with 5000 gals cont ght. ISDP 1400 psi. D BPM. load oil. ment30 bbls oi	vith 110 gals Tretoli 500 gals X-E frac pad 50wed with 5000 gals co aining 4 PPG 20/40 so Maximum treating p	te gyp chemical in 20 , followed with 2500 gals ontaining 3 PPG 20/40 and, flushed with oil ressure 2200 ps , averago NAY 291973 NAY 291973 SUK
30 - barr cont sand Shut pump •22-73Reco	7/8" ball els of wate aining 2 P , followed in overnig ing rate 20 overed all r to treate	sealers, followed w er, followed with 19 PG 20/40 sand, follo with 5000 gals cont ght. ISDP 1400 psi. D BPM. load oil. ment30 bbls oi	ith 110 gals Tretoli 500 gals X-E frac pad owed with 5000 gals co aining 4 PPG 20/40 so Maximum treating p 1, 360 bbls water.	te gyp chemical in 20 , followed with 2500 gals ontaining 3 PPG 20/40 and, flushed with oil ressure 2200 ps , averago NAY 291973 NAY 291973 SUK
30 - barr cont sand Shut pump •22-73Reco	7/8" ball els of wate aining 2 P , followed in overnig ing rate 20 overed all r to treate	sealers, followed w er, followed with 19 PG 20/40 sand, follo with 5000 gals cont ght. ISDP 1400 psi. D BPM. load oil. ment30 bbls oi	ith 110 gals Tretoli 500 gals X-E frac pad owed with 5000 gals co aining 4 PPG 20/40 so Maximum treating p 1, 360 bbls water.	te gyp chemical in 20 , followed with 2500 gals ontaining 3 PPG 20/40 and, flushed with oil ressure 2200 ps , averago NAY 291973 NAY 291973 SUK
30 - barr cont sand Shut pump •22-73Reco	7/8" ball els of wate aining 2 P , followed in overnig ing rate 20 vered all r to treate test avera	sealers, followed w er, followed with 19 PG 20/40 sand, follo with 5000 gals cont ght. ISDP 1400 psid D BPM. load oil. ment30 bbls oi aged 74 bbls oil and	ith 110 gals Tretoli 500 gals X-E frac pad owed with 5000 gals co aining 4 PPG 20/40 so Maximum treating p 1, 360 bbls water.	te gyp chemical in 20 , followed with 2500 gals ontaining 3 PPG 20/40 and, flushed with oil ressure 2200 ps , averago NAY 291973 NAY 291973 SUK
30 - barr cont sand Shut pump •22-73Reco Prio •27-73Well	7/8" ball els of wate aining 2 P , followed in overnig ing rate 20 vered all r to treate test avera	sealers, followed w er, followed with 19 PG 20/40 sand, follo with 5000 gals cont ght. ISDP 1400 psid D BPM. load oil. ment30 bbls oi aged 74 bbls oil and	ith 110 gals Tretoli 500 gals X-E frac pad owed with 5000 gals co aining 4 PPG 20/40 so Maximum treating p 1, 360 bbls water.	te gyp chemical in 20 , followed with 2500 gals ontaining 3 PPG 20/40 and, flushed with oil ressure 2200 ps, average NAY 291973 SUK S. GEOLOGIA SUK S. GEOLOGIA SUK
30 barr cont sand Shut pump -22-73Reco Prio -27-73Well 18. I hereby certify f SIGNED	7/8" ball els of wate aining 2 P , followed in overnig ing rate 20 overed all r to treate test avera	sealers, followed w er, followed with 19 PG 20/40 sand, follo with 5000 gals cont ght. ISDP 1400 psi. D BPM. load oil. nent30 bbls oi aged 74 bbls oil and is true and correct	vith 110 gals Tretoli 500 gals X-E frac pad owed with 5000 gals co aining 4 PPG 20/40 so Maximum treating p 1, 360 bbls water. 1 386 bbls water per o	te gyp chemical in 20 , followed with 2500 gals ontaining 3 PPG 20/40 and, flushed with oil ressure 2200 ps , averago NAY 291973 NAY 291973 SUK
30 barr cont sand Shut pump -22-73Reco Prio -27-73Well 18. I hereby certify f SIGNED	7/8" ball els of wate aining 2 P , followed in overnig ing rate 20 vered all r to treate test avera test avera	sealers, followed w er, followed with 19 PG 20/40 sand, follo with 5000 gals cont ght. ISDP 1400 psi. D BPM. load oil. nent30 bbls oi aged 74 bbls oil and is true and correct fise use) TITLE	vith 110 gals Tretoli 500 gals X-E frac pad owed with 5000 gals co aining 4 PPG 20/40 so Maximum treating p 1, 360 bbls water. 1 386 bbls water per o	te gyp chemical in 20 , followed with 2500 gals ontaining 3 PPG 20/40 and, flushed with oil ressure 2200 ps, average NAY 291973 SUK S. GEOLOGIA SUK S. GEOLOGIA SUK
30 barr cont sand Shut pump -22-73Reco Prio -27-73Well 18. I hereby certify f SIGNED (This space for H APPROVED BY	7/8" ball els of wate aining 2 P , followed in overnig ing rate 20 vered all r to treate test avera test avera	sealers, followed w er, followed with 19 PG 20/40 sand, follo with 5000 gals cont ght. ISDP 1400 psi. D BPM. load oil. nent30 bbls oi aged 74 bbls oil and is true and correct fise use) TITLE	Dist. Supt.	te gyp chemical in 20 , followed with 2500 gals ontaining 3 PPG 20/40 and, flushed with oil ressure 2200 ps , averago NAY 291973 NAY 291973 SUK S. GEOLOU S. GEOLOU S. S. S
30 barr cont sand Shut pump -22-73Reco Prio -27-73Well 18. I hereby certify f SIGNED (This space for H APPROVED BY	7/8" ball els of wate aining 2 P , followed in overnig ing rate 20 vered all r to treate test avera test avera	sealers, followed with 19 PG 20/40 sand, follow with 5000 gals cont ght. ISDP 1400 psi. D BPM. load oil. nent30 bbls oi aged 74 bbls oil and is true and correct fist rue and correct	Dist. Supt.	te gyp chemical in 20 , followed with 2500 gals ontaining 3 PPG 20/40 and, flushed with oil ressure 2200 ps , averago NAY 291973 NAY 291973 SUK S. GEOLOU S. GEOLOU S. S. S