

N. M. O. & G. COPY
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on
reverse side)

Copy to SF
Form approved
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-028978-"a"

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

-

7. UNIT AGREEMENT NAME

-

8. FARM OR LEASE NAME

L.R. Manning 'A' Federal

9. WELL NO.

5

10. FIELD AND POOL, OR WILDCAT

Leo Queen Grayburg

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 21, T-18-S, R-30-E

12. COUNTY OR PARISH 13. STATE

Eddy

New Mexico

1. OIL ☒ GAS ☐ OTHER ☐
WELL WELL

MAR 21 1977

2. NAME OF OPERATOR

TEXACO Inc.

O. C. C.
ARTESIA, OFFICE

3. ADDRESS OF OPERATOR

P. O. Box 728 - Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface Well is located 1980' FWL & 660' FNL of

Section 21, T-18-S, R-30-E, Unit Letter 'C', Eddy County,
New Mexico.

14. PERMIT NO.

Regular

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3481' (DF)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OF ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETION ☐

ABANDON* ☒

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Set CIBP at 2550', dump 35' (4 sx) cement plug on top.
2. Load hole with mud (25 sx gel per 100 bbls water).
3. Spot 100' (10 sx) cement plug across base of salt section at 1300'.
4. Spot 100' (10 sx) cement plug across top of salt section at 480'.
5. Spot 20' (2 sx) cement plug at surface.
6. Install marker and clean location.

RECEIVED

MAR 17 1977

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Asst. District Supt.

DATE 3-16-77

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

MAR 21 1977

ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side