

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME W. Loco Hills G 4S UT
2. NAME OF OPERATOR Newmont Oil Company	8. FARM OR LEASE NAME Tract 8A
3. ADDRESS OF OPERATOR P.O. Box 1305, Artesia, New Mexico	9. WELL NO. 3
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 2600' FNL and 1200' FWL of Section 10; T-12-S, R-29-E	10. FIELD AND POOL, OR WILDCAT Loco Hills
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3494 Gr
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 10 - 18S - 29E
	12. COUNTY OR PARISH Eddy
	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	☐	PULL OR ALTER CASING	☐
FRACTURE TREAT	☐	MULTIPLE COMPLETE	☐
SHOOT OR ACIDIZE	☐	ABANDON*	☐
REPAIR WELL	☐	CHANGE PLANS	☐
(Other)	☐		☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	☐	REPAIRING WELL	☐
FRACTURE TREATMENT	☐	ALTERING CASING	☐
SHOOTING OR ACIDIZING	☐	ABANDONMENT*	☐
(Other) Well Completion	☐		☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

This producing well was drilled with Rotary Rig and completed as follows:

4/13/67

Spudded and drilled to top of salt. Set 382' of 8 5/8" OD 20# casing with 50 sacks cement. Drilled to 2537' and core from 2537 to 2603' then drill to TD of 2626'. Run 2620' of 4 1/2" OD 9.5# casing and cement with 150 sacks. Perforate with 1 shot per foot from 2566 to 2575. Acidize with 1000 gallons 15% acid then frac with 320 bbls. salt water with 10,500# of 10/20 sand. Put well on production 5-1-67; production for 24 hours 1 B0 and -0- water.

18. I hereby certify that the foregoing is true and correct

SIGNED H. J. [Signature]

TITLE Division Superintendent

DATE May 16, 1967

(This space for Federal or State office use)

APPROVED BY H. L. BEEKMAN
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

RECEIVED
MAY 17 1967
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

APPROVED
MAY 22 1967
H. L. BEEKMAN
ACTING DISTRICT ENGINEER

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.