N. M. O. C. C. Dura Form approved. Budget Bureau No. 42-R1424. "ITED STATES SUBMIT IN T ICATE* DEPART, _NT OF THE INTERIOR (Other Instruc. 5. LEASE DESIGNATION AND SERIAL NO. T.C-026874 - (F)GEOLOGICAL SURVEY 6. IF INDIAN, ALLOTTEE OR TRIBE NAME SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.) 7. UNIT AGREEMENT NAME WELL WELL X Drilling OTHER 2. NAME OF OPERATOR 8. FARM OR LEASE NAME Welch Federal Humble Oil & Refining Company 9. WELL NO. ADDRESS OF OPERATOR P. O. Box 1600, Midland, Texas LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) 10. FIELD AND POOL, OR WILDCAT 11. SEC., T., B., M., OR BLE. AND SURVEY OR AREA 1980' FNL & 660' FEL S6-T18S-R27E 14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 12. COUNTY OR PARISH 13. STATE 3469' DF Eddy N. Mex. 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF REPAIRING WELL FRACTURE TREAT MULTIPLE COMPLETE FRACTURE TREATMENT ALTERING CASING X SHOOT OR ACIDIZE ABANDON* SHOOTING OR ACIDIZING ABANDON MENT REPAIR WELL CHANGE PLANS (Other) . (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) Well reached TD @ 3140' on 5-31-67. Subsequent testing revealed the well to be dry. We request permission to plug and abandon the well as follows: Set 25 sx cement plug from 2907-2650'. Set 10 sx cement plug in 8 5/8" and 7 5/8" casing annulus. Set 10 sx cement plug in 7 5/8" and 4 1/2" casing annulus. Install top plug from 30' to surface. Install dry hole marker in top plug. Clean and level location. 18. I hereby certify that the foregoing as true and correct Agent 7-6-67 SIGNED TITLE DATE

(This space for Federal or State office use)

APPROVED BY

APPROVAL IF ANY:

DATE

DATE

TITLE

DATE

See Instructions on Reverse Side