

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

REFILED
NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-6458
7. Unit Agreement Name
8. Farm or Lease Name State "BI"
9. Well No. 1
10. Field and Pool, or Wildcat Wildcat
12. County Eddy

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Drilling
2. Name of Operator Atlantic Richfield Company
3. Address of Operator P. O. Box 1978, Roswell, New Mexico
4. Location of Well UNIT LETTER F , 1980 FEET FROM THE North LINE AND 1980 FEET FROM THE West LINE, SECTION 33 TOWNSHIP 18-S RANGE 25-E N.M.P.M.
15. Elevation (Show whether DF, RT, GR, etc.) 3591' DF

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
OTHER <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well was drilled (8-3/4" hole) to a T.D. of 10,130' without encountering commercial hydrocarbons. We propose to P & A by setting the following neat Incor cement plugs:

30 sx from 9668-9768
45 sx from 8768-8918
30 sx from 7290-7390
30 sx from 5450-5550

30 sx from 4050-4150
30 sx from 1947-2047
30 sx from 972-1072
10 sx from 17- 41

9.6#/gal gel mud will be used to spot all plugs. Location will be cleared and dry hole marker erected. 13-3/8" & 9-5/8" casing strings will remain intact.

Verbal permission received for above program from Mr. W. A. Gressett on October 4, 1967.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Original Signed	TITLE	DATE
SIGNED O. D. Bretches	Dist. Drlg. Supervisor	10-6-67
APPROVED BY <i>W. A. Gressett</i>	TITLE	DATE 1967
CONDITIONS OF APPROVAL, IF ANY:		