

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	/
FILE	/
U.S.G.S.	
LAND OFFICE	
OPERATOR	/

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <b>Len Mayer</b>	8. Farm or Lease Name <b>Costa Plente Gas Com</b>
3. Address of Operator <b>c/o Oil Reports and Gas Services, Box 763, Hobbs, New Mexico</b>	9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>A</b> , <b>990</b> FEET FROM THE <b>North</b> LINE AND <b>990</b> FEET FROM THE <b>East</b> LINE, SECTION <b>32</b> TOWNSHIP <b>18 S</b> RANGE <b>26 E</b> NMPM.	10. Field and Pool, or Wildcat <b>Undes Atoka Penn Gas</b>
15. Elevation (Show whether DF, RT, GR, etc.)	12. County <b>Eddy</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

To confirm verbal approval from Bill Gressett to  
Jack Brown on 11/4/68 to plug as follows:

25 sacks at top perfs  
25 sacks at 4 1/2" casing stub  
30 sacks at top Wolfcamp at 5995  
30 sacks at top Abo at 4610  
30 sacks at 8 5/8" casing shoe at 1211  
30 sacks at top San Andres at 935-600  
10 sacks at surface with regulation marker.  
Mud between all plugs.

Location to be cleared and levelled.

RECEIVED

FEB 5 1969

O. C. C.  
ARTESIA, OFFICE

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. L. Smith TITLE Agent DATE 1/30/69

APPROVED BY W. A. Gressett TITLE OIL AND GAS INSPECTOR DATE FEB 5 1969

CONDITIONS OF APPROVAL, IF ANY: