

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

NOV 21 1980

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. NM 647	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- WATER INJECTION WELL		7. Unit Agreement Name
2. Name of Operator BOYD OPERATING COMPANY		8. Farm or Lease Name Rotary State
3. Address of Operator P. O. Box 1756, Roswell, New Mexico 88201		9. Well No. 7
4. Location of Well UNIT LETTER J 2650 W 2650 THE N 20 18S 28E LINE, SECTION TOWNSHIP RANGE NMPM.		10. Field and Pool, or Wildcat Art. Qn Gbg S.A.
15. Elevation (Show whether DF, RT, GR, etc.) 3859 G.L.		12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10/16/80 Rigged up. Ran cement retainer and 63 jts of 2 7/8" tubing. Set at 1902' and squeezed with 65 sacks at 1200 psi on last 10 sacks. Pulled 4 1/2" csg. Csg. parted.

10/17/80 Cut csg. at 1250'. Ran center spear and pulled 4 1/2" csg. Spotted 40 sx. plug across stub of 4 1/2" casing.

10/18/80 Tagged cement. Pumped 100 sx. Tagged top of cement at 676'. Pumped 55 sx. across 8 5/8" surface. Tagged cement at 460'. Spot 10 sx plug at surface and set marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J M Boyd TITLE Operator DATE 11/20/80

APPROVED BY Mike Sturges TITLE OIL AND GAS INSPECTOR DATE FEB 02 1981

CONDITIONS OF APPROVAL, IF ANY: