

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. LC 029388D	
2. NAME OF OPERATOR Harvey E. Yates Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR P.O. Box 1933, Roswell, New Mexico 88201		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 660' FNL & 660' FWL		8. FARM OR LEASE NAME Mesquite 3 Federal	
14. PERMIT NO. API 30-015-20107		9. WELL NO. 1	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3751.7'		10. FIELD AND POOL, OR WILDCAT N. Shugart Bone Spring	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 3, T18S, R31E	
		12. COUNTY OR PARISH Eddy	
		13. STATE NM	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) P&A <input type="checkbox"/>	
(Other) <input type="checkbox"/>		(NOTE: Report results of multiple completion or Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

9-8-87 Set 5 1/2" CIBP @ 7675' w/35' cmt on top. Circ hole w/salt gel mud.
9-9-87 Pump 40 sx plug from 5500'-5400'. Pumped 100 sx plug from 5050'-4750'. Cut 5 1/2" csg @ 4618', pumped 40 sxs plug @ 4670'-4520'. Tag plug @ 4520'. Circ hole clean w/9# salt mud.
9-10-87 Free point 9 5/8" csg @ 1009'. Cut & pull 1009' 9 5/8" csg.
9-11-87 Pump 75 sxs plug @ 1060'. Tag plug @ 900'. Pump 85 sxs plug from 800-700' and tagged.
9-12-87 Pumped 50' surface plug & installed dry hole marker. P & A complete.

ACCEPTED FOR RECORD

SEP 28 1987

SJS

CARLSBAD, NEW MEXICO

SEP 22 11 55 AM '87
CARLSBAD, NEW MEXICO

RECEIVED

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Production Manager/Engineer

DATE September 21, 1987

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

Post ID-2
10-2-87
P&A

Approved by _____
Liability on the _____ until _____

*See Instructions on Reverse Side

Title 18 U.S.C. Section 1001 makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.