

NO. OF COPIES RECEIVED	2
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	3

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator The Fundamental Oil Corporation		8. Farm or Lease Name Thorp-Sears Com.
3. Address of Operator 516 Gulf Building, Midland, Texas 79701		9. Well No. 1
4. Location of Well UNIT LETTER <u>P</u> <u>990</u> FEET FROM THE <u>South</u> LINE AND <u>990</u> FEET FROM THE <u>East</u> LINE, SECTION <u>18</u> TOWNSHIP <u>18S</u> RANGE <u>26E</u> NMPM.		10. Field and Pool, or Wildcat Atoka Penn. Und.
15. Elevation (Show whether DF, RT, GR, etc.) 3412 GR		12. County Eddy

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

It is our intention to Plug and Abandon this well as follows:  
Trip to bottom with open-ended 4½" drillpipe to 8970'. Circulate 9.4#, 100 vis. mud for 2 hrs. Place Class "C" Incor 35 sx plugs in 7-7/8" hole as follows:

35 sx 8800-8660 (Morrow)  
35 sx 7000-6860 (Cisco)  
35 sx 5700-5560 (Wolfcamp)  
35 sx 4300-4160 (Abo)  
35 sx 2100-1960 (Glorietta)  
35 sx 1200-1060 (In and out of 8-5/8" csg.)  
35 sx 700-560 (Between Grayburg & San Andres)

Place a 4" x 4' properly identified marker in 8-5/8" casing. Fill cellar with Read-Mix. Clean location and level pits.

RECEIVED

NOV 15 1968

C. C. E.  
ARTESIA, OFFICE

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Paul White TITLE Engineer DATE 11-14-68

APPROVED BY W. A. Gressett TITLE OIL AND GAS INSPECTOR DATE NOV 15 1968

CONDITIONS OF APPROVAL, IF ANY: