Form 9-331 (May 1963)	U'─TED S' DEPARTMLNT OF T GEOLOGICAI	THE INTERIO	C. C. C. C. C. C. A. SUBMIT IN TR CAT SUBMIT IN TR CAT (Other Instructi on R verse side)	
	RY NOTICES AND m for proposals to drill or to se "APPLICATION FOR PER	RÉPORTS ON		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
1. OIL XX GAS WELL WELL 2. NAME OF OPERATOR	OTHER	REC	EIVED	7. UNIT AGREEMENT NAME W. LOCO HILLS G. #4 S 8. FARM OR LEASE NAME
	IL COMPANY -	JAN	1 2 1973	Tract 12
3. Address of operator P O BOX	1305, Artesia, Ne	ew Mexico 🗕	<b> #</b> \$210	9. WELL NO.
<ol> <li>LOCATION OF WELL (Repo See also space 17 below.) At surface</li> </ol>	rt location clearly and in acc	ordance with any St	te requirements.*	10. FIELD AND POOL, OR WILDCAT LOCO Hills
1650' FSL & 1750 FEL Section 9				11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 9-185-29E
14. PERMIT NO.	15. ELEVATIONS	Show whether DF, RT	, GR, etc.)	12. COUNTY OR PARISH 13. STATE
		3490' GL		Eddy N.M.
16.	Check Appropriate Box	. To Indicate Nat	ure of Notice, Report, o	r Other Data
NOT	ICE OF INTENTION TO:		SUBS	SEQUENT REPORT OF:
TEST WATER SHUT-OFF	PULL OR ALTER C		WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT SHOOT OR ACIDIZE	MULTIPLE COMPL.	ETE	FRACTURE TREATMENT	XX ALTERING CASING
REPAIR WELL	ABANDON* CHANGE PLANS		SHOOTING OR ACIDIZING	ABANDONMENT*
(Other)			(NOTE : Report resi	ults of multiple completion on Well- mpletion Report and Log form.)
11/9/72: Cla sea 20, Ave 11/11/72: Cha P	alers, 110 gals gy /40 sand. Max. pr g. treating rate 2 ecked for fill up roduced 94 BOPD a	2556'. Pump yp chemical, ressure 2700# 21.7 BPM	ed 500 gals HCL c and frac'd w/14,0 psi, avg. 2600# and rods, put wel before frac	containing 48 - 7/8" ball 000 gals oil and 40,000# psi, 1SDP 1650# psi.
8. Thorphy postily that it	Powegel w Ja +			4 S CAN 1 1 9-3
SIGNED _ Charlie	foregoing is true and correc		t. Supt.	1/8/73
(This space for Federal	or State office use)	······		
APPROVED BY		TITLE		DATE
DDR 11,437	OVAL IF ANY:			
JAP BUNNAN	EEI *	See Instructions o	n Reverse Side	
ACTING DISTRICT ENCIN				