

NO. OF COPIES RECEIVED	5
DISTRIBUTION	
SANTA FE	/
FILE	/
U.S.G.S.	
LAND OFFICE	
OPERATOR	/

**RECEIVED**  
NEW MEXICO OIL CONSERVATION COMMISSION

OCT 8 1971

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

**O. C. C.**

ARTESIA, OFFICE

**SUNDRY NOTICES AND REPORTS ON WELLS**

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- 2. Name of Operator <b>C. E. Poach Drilling Company</b> ✓ 3. Address of Operator <b>P. O. Box Box 157 - Artesia, New Mexico 88210</b> 4. Location of Well UNIT LETTER <b>H</b> <b>2310</b> FEET FROM THE <b>North</b> LINE AND <b>330</b> FEET FROM THE <b>East</b> LINE, SECTION <b>18</b> TOWNSHIP <b>18S</b> RANGE <b>28E</b> NMPM.	5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/> 5. State Oil & Gas Lease No. <b>E 828</b> 7. Unit Agreement Name 8. Farm or Lease Name <b>Bulf State</b> 9. Well No. <b>IX 1</b> 10. Field and Pool, or Wildcat <b>Artesia</b> 12. County <b>Eddy</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>GR 3608</b>	

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <input type="checkbox"/>
--	--

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**We intend to plug the above well as follows:**

**Plug from TD of 2260' back to 2100' w/ready mix.  
 Fill with mud from 2100' to 1520'  
 Set plug from 1520' to 1420' w/25 sacks cement  
 Fill with mud from 1420' to 475'  
 Set plug from 475' to 375' w/25 sacks cement  
 Fill with mud from 375' to surface  
 Set surface plug with marker w/10 sacks cement.**

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *C. E. Poach* TITLE Owner DATE October 7, 1971

APPROVED BY *W. A. Gressett* TITLE OIL AND GAS INSPECTOR DATE OCT 8 1971

CONDITIONS OF APPROVAL, IF ANY: