

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

RECEIVED

5a. Indicate Type of Lease  
State  Fee

5. State Oil & Gas Lease No. **L-121**

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSAL.)

MAY 28 1975

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <b>The Eastland Oil Company</b>	8. Farm or Lease Name <b>Allied State</b>
3. Address of Operator <b>704 Western United Life Building, Midland, Texas 79701</b>	9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>M</b> <b>330</b> FEET FROM THE <b>South</b> LINE AND <b>660</b> FEET FROM THE <b>West</b> LINE, SECTION <b>32</b> TOWNSHIP <b>17-S</b> RANGE <b>31-E</b> NMPM.	10. Field and Pool, or Wildcat <b>San Pover Grayburg Andros</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3,691 GL, 3,701 DP (ref.)</b>	12. County <b>Eddy</b>

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

On May 1, 1975 moved in Howard Boatright Co. rig and pulled tubing. Set cast iron bridge plug at 3,450 feet with wire line and dumped 20' cement on top to 3,430 feet in 4 1/2" csg. Cut 4 1/2" csg. at 2,209 feet and pulled. Ran tubing and circulated hole with 100 mud. Set additional plugs as follows:

2,207' to 2,107' with 35 sx in 7 7/8" hole at top of 4 1/2" csg.

1,645' to 1,545' with 35 sx at base of salt.

748' to 648' in and out of 8 5/8" csg. with 35 sx.

45' to surface in 8 5/8" csg. with 15 sx.

Set 4 1/2" OD x 4' marker in top of casing. Notice will be sent as soon as location is cleared of material and ready for inspection. Work completed May 8, 1975.

Casing left in hole:

1,441' - 4 1/2", 9.50 casing from 2,209' to 3,650'.

700' - 8 5/8", 200 casing from surface to 700' w/cement circ.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED George P. Neal TITLE Superintendent DATE 5/21/75

APPROVED BY Lelan Mermis TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: