

15. I would prefer to recommend a plugging program at the time of actual plugging.

16. An unreasonable length of time has passed with out any action being taken. -

17. yes

(3)

Actna Casualty & Surety Co.
\$10,000 blanket cancelled to
future operations 8-30-75

9-13-78

Case 6316 Cortez Corp.
Bill Jones oil Co.

Fair #1 - located 330' FNL + 330' FWL 1 sec. 24 T18s R-26C
Form C-101 - approved 2-16-71

spud. 2-19-71 Coplump.

d to TD of 1925 Cons for Prod.

C-103 surface csg. report app. 2-26-71

" " Prod. csg. " app. 3-15-71

Form C-104 request for allowablr. app. 4-19-71

Cortez oil Corp. filed Form C-104 Reporting a change
in ownership on 4-17-75

~~had~~ no production reported since 12-76 -

Cumpr Prod. 4027 bbls.

letter of 6-23-78 no response -

letter ~~from~~ 8-2-78 from -

We were contacted by ~~someone with~~

Mr. P. + he ~~did not~~

opposed to plugging the well if we would give
him some time -

9-6-78 Tubing + Rods in hole - Pump Jack -
tank ~~at~~ bty + Hester tractor.

4 1/2" - 1924 - 175 mks. TCC-960
Copy for Problem on 4-3-29-71

changed

Carly Corp. filed Form 104 reporting a
change in ownership on 4-17-75