

N. M. O. C. C. CORY
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSTAMP
(Other
verse side)TRIPLICATE
copies on re-Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-025608

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

None

7. UNIT AGREEMENT NAME

Socogin Draw Deep Unit

8. FARM OR LEASE NAME

Socogin Draw Deep Unit

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLM. AND
SURVEY OR AREA

Sec. 31-18S-27E

12. COUNTY OR PARISH 13. STATE

Eddy

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT-" for such proposals.)1. OIL WELL ☐ GAS WELL ☒ OTHER ☐ Water Source Well

2. NAME OF OPERATOR

Read & Stevens, Inc.

3. ADDRESS OF OPERATOR

P. O. Box 2126, Roswell, New Mexico 88201

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1980' FEL & 660' FSL, Sec. 31, T-18-S, R-27-E, N.M.P.M.

14. PERMIT NO.

-

15. ELEVATIONS (Show whether DF, RT, CR, etc.)

3276.4 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☒CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion or Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

1. Received verbal approval via telephone 5/22/72.
2. Set 20' cement plug in bottom of surface.
3. Fill casing with mud.
4. Set 10' cement plug in top of casing.
5. Install regulation marker.

JUL 13 1972

JUL 13 1972
U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

RECEIVED

JUL 13 1972

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

C. L. Schellinger

TITLE

Agent

DATE July 10, 1972

(This space for Federal or State office use)

TITLE

DATE

APPROVED
JUL 14 1972APPROVED BY
CONDITIONAL APPROVAL, IF ANY:R. L. BEEKMAN
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side