		N. M. O. C. C	C. COPY	e en
Form 9-331 (May 1963)	L .TED DEPARTMENT OF	STATES THE INTERIOF	(Other Instantions on	TE* re 5. LEASE DESIGNATION AND SERIAL NO. NM-025503
(Do not use t	INDRY NOTICES AN bis form for proposals to drill o Use "APPLICATION FOR F	D REPORTS ON	WELLS to a difference en rvoir.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
		_	REC 8 PI	T. UNIT AGREEMENT NAME
WELL WEL 2. NAME OF OPERATOR	i /	1016	- OF ANI	8. FARM OR LEASE NAME Ginsberg Federal
3. ADDRESS OF OPERA		,	U. ARTIE	9. WELL NO. #7
P. O. BOX 4. LOCATION OF WELL See also space 17	(Report location clearly and in below.)	New Mexico accordance with any Sta	88201 te requirements.*	10. FIELD AND POOL, OR WILDCAT
At surface	990' FEL & .	1650' FSL 18-S, R-30-E,	NMPM	Shugart 11. BEC., T., E., M., OF BLK. AND SUBVET OF AREA
	<b>-</b> ,	, New Mexico		Sec. 24, T-18S, R-30
14. PERMIT NO.		.8 GL 3641.8		12. COUNTY OF PARISH 13. STATE Eddy New Mexic
16.			ure of Notice, Report,	or Other Data
16.	NOTICE OF INTENTION TO:			BSBQUENT REPORT OF:
TEST WATER SHU Fracture treat	T-OFF PULL OR ALT		WATER SHUT-OFF Fracture treatment	ALTERING CASING
SHOOT OR ACIDIZ	E ABANDON* CHANGE PLAN	X X	SHOOTING OR ACIDIZING	
REPAIR WELL (Other)			(Note: Report r Completion or Re	esults of multiple completion on Well completion Report and Log form.) dates, including estimated date of starting any vertical depths for all markers and zones perti-
35 sx. @ 39 40 sx. @ 33 35 sx. @ 17	360-3500'	s follows:		·
	are to be set in on marker set.	heavy mud.	Location will	l be cleaned up and
				RECEIVED DEC 9 1971
				D. C. C. ARTESIA, OFFICE
18. I hereby certify SIGNED	that, the foregoing/is true and and E. Annall	/-	Geologist	DATE <u>12-7-71</u>
SOD	FAEPROVAL IF ANY:	TITLE	<u></u>	DATE
R. L. BEEK	See 2	*See Instructions (	on Reverse Side	