	130 · 1410 · · · · · · · · · · · · · · · · · · ·		
1 MAY 10007	L .TED STATES MENT OF THE INTERIC	SUBMIT IN TRA CAT (Other instructions on	
		JR verse side)	
(GEOLOGICAL SURVEY	·····	NM-025503 6. IF INDIAN, ALLOTTEE OR THE NAME
	ICES AND REPORTS O sals to drill or to deepen or plug bac ATION FOR PERMIT—" for such prop		
I. OIL GAS WELL WELL OTHER		······	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR			8. FARM OR LEASE NAME
Hanson Oil Corpor 3. ADDRESS OF OPERATOR	ation /		Ginsberg Federal 9. WELL NO.
P. O. Box 1515 -	Roswell, New Mexic	o 88201	#8
4. LOCATION OF WELL (Report location of See also space 17 below.)	clearly and in accordance with any St	tate requirements.*	10. FIELD AND POOL, OB WILDCAT
At suffare	330' FEL		Shugart de la
	2-18-S, R-30-E, NMP)M	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
•	•		
Eddy Count	y, New Mexico		Sec. 26, T-18S, R-3
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, R	IT, GR, etc.)	12. COUNTY OB PARISH 13. STATE
	3508.9 GL		Eddy New Mex
16. Check Ar	ppropriate Box To Indicate Na	ture of Notice Report	Other Data
NOTICE OF INTEN	NTION TO:	SUBS	EQUENT REPORT OF:
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT*
REPAIR WELL	CHANGE PLANS	(Other) <u>5支" Cas</u>]	Ing report X
(Other)		Completing to Been	mulation Bapart and Lon form)
nent to this work.)*	dolomite. Cut & p	details, and give pertinent dat ns and measured and true ver oulled 8-3/8" Cs	
nent to this work.)* 11-5-71 T.D. 3550' 11-6-71 Ran 5½" 15.	dolomite. Cut & p 5# casing to 3545'	details, and give pertinent dat ns and measured and true ver oulled 8-3/8" cs . Cemented w/9	es, including estimated date of starting an tical depths for all markers and zones perf 59. 2000 sx. HOWCO Lite Wat
nent to this work.)* 11-5-71 T.D. 3550' 11-6-71 Ran 5½" 15. w/5# Gilson	dolomite. Cut & p 5# casing to 3545, hite/sx + 250 sx. o	details, and give pertinent dat ns and measured and true ver oulled 8-3/8" Cs . Cemented w/9 of Class H w/5#	es, including estimated date of starting an tical depths for all markers and zones perf 59. 000 sx. HOWCO Lite Wat salt/sx. & 10# sand/s
nent to this work.)* 11-5-71 T.D. 3550' 11-6-71 Ran 5½" 15. w/5# Gilson 11-7-71 Cement did	dolomite. Cut & p 5# casing to 3545' hite/sx + 250 sx. o not circulate. Ce	details, and give pertinent dat ns and measured and true ver oulled 8-3/8" cs . Cemented w/9 of Class H w/5# emented using l'	es, including estimated date of starting an tical depths for all markers and zones perf 59. 000 sx. HOWCO Lite Wat salt/sx. & 10# sand/s ' tubing.
nent to this work.)* 11-5-71 T.D. 3550' 11-6-71 Ran 5½" 15. w/5# Gilson	dolomite. Cut & p 5# casing to 3545' hite/sx + 250 sx. o not circulate. Ce	details, and give pertinent dat ns and measured and true ver oulled 8-3/8" cs . Cemented w/9 of Class H w/5# emented using l'	es, including estimated date of starting an tical depths for all markers and zones perf 59. 000 sx. HOWCO Lite Wat salt/sx. & 10# sand/s ' tubing.
nent to this work.)* 11-5-71 T.D. 3550' 11-6-71 Ran 5½" 15. w/5# Gilson 11-7-71 Cement did	dolomite. Cut & p 5# casing to 3545' hite/sx + 250 sx. o not circulate. Ce	details, and give pertinent dat ns and measured and true ver oulled 8-3/8" cs . Cemented w/9 of Class H w/5# emented using l'	es, including estimated date of starting an tical depths for all markers and zones perf 59. 000 sx. HOWCO Lite Wat salt/sx. & 10# sand/s ' tubing. one hour. No leaks.
nent to this work.)* 11-5-71 T.D. 3550' 11-6-71 Ran 5½" 15. w/5# Gilson 11-7-71 Cement did	dolomite. Cut & p 5# casing to 3545 ite/sx + 250 sx. o not circulate. Ce 45'. Tested casin	details, and give pertinent dat ns and measured and true ver oulled 8-3/8" cs . Cemented w/9 of Class H w/5# emented using l' ng @ 1000# for c	es, including estimated date of starting an tical depths for all markers and zones perf 59. 000 sx. HOWCO Lite Wat salt/sx. & 10# sand/s ' tubing. one hour. No leaks.
nent to this work.)* 11-5-71 T.D. 3550' 11-6-71 Ran 5½" 15. w/5# Gilson 11-7-71 Cement did	dolomite. Cut & p 5# casing to 3545 ite/sx + 250 sx. o not circulate. Ce 45'. Tested casin	details, and give pertinent dat ns and measured and true ver oulled 8-3/8" cs . Cemented w/9 of Class H w/5# emented using l'	es, including estimated date of starting an tical depths for all markers and zones perf 59. 000 sx. HOWCO Lite Wat salt/sx. & 10# sand/s ' tubing. one hour. No leaks.
nent to this work.)* 11-5-71 T.D. 3550' 11-6-71 Ran 5½" 15. w/5# Gilson 11-7-71 Cement did	dolomite. Cut & p 5# casing to 3545 ite/sx + 250 sx. o not circulate. Ce 45'. Tested casin	details, and give pertinent dat ns and measured and true ver oulled 8-3/8" cs . Cemented w/9 of Class H w/5# emented using l' ng @ 1000# for c	REC No.
nent to this work.)* 11-5-71 T.D. 3550' 11-6-71 Ran 5½" 15. w/5# Gilson 11-7-71 Cement did	dolomite. Cut & p 5# casing to 3545 hite/sx + 250 sx. o not circulate. Ce 45'. Tested casin RECE	details, and give pertinent dat ns and measured and true ver oulled 8-3/8" cs . Cemented w/9 of Class H w/5# emented using 1' ag @ 1000# for c	es, including estimated date of starting an tical depths for all markers and zones perf 5g. 000 sx. HOWCO Lite Wat salt/sx. & 10# sand/s ' tubing. one hour. No leaks. RECENTED U.S. NOV 15 1971
nent to this work.)* 11-5-71 T.D. 3550' 11-6-71 Ran 5½" 15. w/5# Gilson 11-7-71 Cement did	dolomite. Cut & p 5# casing to 3545 hite/sx + 250 sx. o not circulate. Ce 45'. Tested casin RECE	details, and give pertinent dat ns and measured and true ver oulled 8-3/8" cs . Cemented w/9 of Class H w/5# emented using l' ng @ 1000# for c	es, including estimated date of starting an tical depths for all markers and zones perf 5g. 000 sx. HOWCO Lite Wat salt/sx. & 10# sand/s ' tubing. one hour. No leaks. RECENTED U.S. NOV 15 1971
nent to this work.)* 11-5-71 T.D. 3550' 11-6-71 Ran 5½" 15. w/5# Gilson 11-7-71 Cement did	dolomite. Cut & p 5# casing to 3545 hite/sx + 250 sx. o not circulate. Ce 45'. Tested casin RECE NOV 1	details, and give pertinent dat ns and measured and true ver oulled 8-3/8" cs . Cemented w/9 of Class H w/5# emented using 1' ag @ 1000# for c EIVED 6 1971	REC No.
nent to this work.)* 11-5-71 T.D. 3550' 11-6-71 Ran 5½" 15. w/5# Gilson 11-7-71 Cement did	dolomite. Cut & p 5# casing to 3545' hite/sx + 250 sx. o not circulate. Ce 45'. Tested casin RECE NOV 1	details, and give pertinent dat ns and measured and true ver oulled 8-3/8" cs . Cemented w/9 of Class H w/5# emented using 1' ag @ 1000# for c 6 1971 5. C.	es, including estimated date of starting an tical depths for all markers and zones perf 5g. 000 sx. HOWCO Lite Wat salt/sx. & 10# sand/s ' tubing. one hour. No leaks. RECENTED U.S. NOV 15 1971
nent to this work.)* 11-5-71 T.D. 3550' 11-6-71 Ran 5½" 15. w/5# Gilson 11-7-71 Cement did 11-8-71 P.B.T.D. 35	dolomite. Cut & p 5# casing to 3545 hite/sx + 250 sx. o not circulate. Ce 45'. Tested casin RECE NOV 1	details, and give pertinent dat ns and measured and true ver oulled 8-3/8" cs . Cemented w/9 of Class H w/5# emented using 1' ag @ 1000# for c 6 1971 5. C.	es, including estimated date of starting an tical depths for all markers and zones perf 5g. 000 sx. HOWCO Lite Wat salt/sx. & 10# sand/s ' tubing. one hour. No leaks. RECENTED U.S. NOV 15 1971
nent to this work.)* 11-5-71 T.D. 3550' 11-6-71 Ran 5½" 15. w/5# Gilson 11-7-71 Cement did	dolomite. Cut & p 5# casing to 3545 hite/sx + 250 sx. o not circulate. Ce 45'. Tested casin RECE NOV 1 	details, and give pertinent dat ns and measured and true ver oulled 8-3/8" cs . Cemented w/9 of Class H w/5# emented using 1' ag @ 1000# for c 6 1971 5. C.	es, including estimated date of starting an tical depths for all markers and zones perf 5g. 000 sx. HOWCO Lite Wat salt/sx. & 10# sand/s ' tubing. one hour. No leaks. RECENTED U.S. NOV 15 1971
<pre>nent to this work.)* ll-5-71 T.D. 3550' ll-6-71 Ran 5½" 15. w/5# Gilson ll-7-71 Cement did ll-8-71 P.B.T.D. 35 </pre>	dolomite. Cut & p 5# casing to 3545' hite/sx + 250 sx. o not circulate. Ce 45'. Tested casin RECE NOV 1 D.C ARTESIA, s true and correct <u>ust</u> <u>TITLE</u> <u>M</u>	details, and give pertinent dat ns and measured and true ver oulled 8-3/8" cs . Cemented w/9 of Class H w/5# emented using l' ag @ 1000# for c 6 1971 C.C.	res, including estimated date of starting an tical depths for all markers and zones performed sg. 000 sx. HOWCO Lite Waths salt/sx. & 10# sand/s ' tubing. one hour. No leaks. $RECNV 0. S. GAN 15.1971 ARTESIA$
<pre>nent to this work.)* ll-5-71 T.D. 3550' ll-6-71 Ran 5½" 15. w/5# Gilson ll-7-71 Cement did ll-8-71 P.B.T.D. 35 ll-8-71 P.B.T.D. 35 i8. I hereby certify that the foregoing to signed the foregoing to signed the foregoing to signed the foregoing to state officient of the space for Folieral or State officient officient</pre>	dolomite. Cut & p 5# casing to 3545' hite/sx + 250 sx. o not circulate. Ce 45'. Tested casin RECE NOV 1 	details, and give pertinent dat ns and measured and true ver oulled 8-3/8" cs . Cemented w/9 of Class H w/5# emented using l' ag @ 1000# for c 6 1971 C.C.	res, including estimated date of starting an tical depths for all markers and zones performed sg. 000 sx. HOWCO Lite Waths salt/sx. & 10# sand/s ' tubing. one hour. No leaks. $RECNV 0. S. GAN 15.1971 ARTESIA$
<pre>nent to this work.)* ll-5-71 T.D. 3550' ll-6-71 Ran 5½" 15. w/5# Gilson ll-7-71 Cement did ll-8-71 P.B.T.D. 35 ll-8-71 P.B.T.D. 35 i8. I hereby certify that the foregoing to signed the foregoing to signed the foregoing to signed the foregoing to state officient of the space for Folieral or State officient officient</pre>	dolomite. Cut & p 5# casing to 3545' hite/sx + 250 sx. o not circulate. Ce 45'. Tested casin RECE NOV 1 RECE NOV 1 CARTESIA , s true and correct <u>ce use</u>)	details, and give pertinent dat ns and measured and true ver oulled 8-3/8" cs . Cemented w/9 of Class H w/5# emented using l' ag @ 1000# for c 6 1971 C.C.	es, including estimated date of starting ar tical depths for all markers and zones perf 5G. 200 sx. HOWCO Lite Wat salt/sx. & 10# sand/s ' tubing. one hour. No leaks.
<pre>nent to this work.)* ll-5-71 T.D. 3550' ll-6-71 Ran 5½" 15. w/5# Gilson ll-7-71 Cement did ll-8-71 P.B.T.D. 35 ll-8-71 P.B.T.D. 35 i8. I hereby certify that the foregoing to signed the foregoing to signed the foregoing to signed the foregoing to state officient of the space for Folieral or State officient officient</pre>	dolomite. Cut & p 5# casing to 3545' hite/sx + 250 sx. o not circulate. Ce 45'. Tested casin RECE NOV 1 	details, and give pertinent dat ns and measured and true ver oulled 8-3/8" cs . Cemented w/9 of Class H w/5# emented using 1' ag @ 1000# for c 6 1971 C.C. OFFICE lanager	es, including estimated date of starting ar tical depths for all markers and zones perf 5G. 200 sx. HOWCO Lite Wat salt/sx. & 10# sand/s ' tubing. one hour. No leaks.