

EMPIRE SOUTH DEEP UNIT NO. 2

1 of 1
From: 2/5/97 07:00:00 To: 2/5/97 18:00:00 11.00 Hrs PLANNED on DURING
Functional Responsibility: OTHER Job Sequence No: 7 ACIDIZING
Operations Description: Acidizing
ACD X 1000 GALS 7.5% X 25,000 N2 X FLUSH X 10 BW X 80,000 N2. SI FOR 15 MINS X SWB EVERY
HR X FOR 6 HRS X REC 4 BLW. IFL 10,300 X FFL 10,300. APX 300-400 FL ENTRY PER HR.

1 of 1
From: 2/6/97 07:00:00 To: 2/6/97 18:00:00 11.00 Hrs PLANNED on DURING
Functional Responsibility: OTHER Job Sequence No: 8 TESTING/SWABBING
Operations Description: Swabbing
TPC 125 PSI X CPC 0 PSI. BLED RIGHT OFF (N2). SWB EVERY HR FOR 10 HRS X REC .5 BLW. IFL
10,300 X FFL 10,500 FS X SION.

1 of 1
From: 2/7/97 07:00:00 To: 2/7/97 12:00:00 5.00 Hrs PLANNED on DURING
Functional Responsibility: OTHER Job Sequence No: 8 TESTING/SWABBING
Operations Description: Swabbing
TPC 80 PSI (N2). R SWB EVERY HR FOR 3 HRS X NO REC. FL 10,500 X SHUT WELL IN X RD X REL
SWB UNIT.
