

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 South First, Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised March 25, 1999

WELL APNO. 30-015-20676

5. Indicate Type of Lease  
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.  
B-5524-24

7. Lease Name or Unit Agreement Name:  
WLHU G4S Unit Tract 29

8. Well No.  
3

9. Pool name or Wildcat  
Loco Hills-Q-GB-San Andres

10. Elevation (Show whether DR, RKB, RT, GR, etc.)  
3511' GR

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
Oil Well ☐ Gas Well ☐ Other Plug & Abandon ☒

2. Name of Operator  
Yates Petroleum Corporation

3. Address of Operator  
105 South Fourth St. - Artesia, NM 88210

4. Well Location  
Unit Letter N : 990 feet from the South line and 2245 feet from the West line  
Section 2 Township 18S Range 29E NMPM Eddy County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)  
3511' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

6-19-2002 - Moved in and rigged up pulling unit and plugging equipment. Rigged up rod equipment. Unseat pump. Shut well in for night.

6-20-2002 - POOH with rods and pump. Rigged down rod equipment. Rigged up tubing equipment. Nippled down wellhead and nipped up BOP. POOH with tubing. Shut well in for night.

6-21-2002 - Finished POOH with tubing. Rigged up wireline. RIH with CIBP and set CIBP at 2576'. POOH with wireline. Capped CIBP with 35' of cement. POOH and rigged down wireline. RIH with tubing. Circulated hole with plugging mud. POOH to 1025'. Spotted 25 sacks Class C Neat cement. POOH. WOC. Shut well in for night.

6-22-24-2002 - RIH with tubing and tagged cement at 657'. POOH to 501'. Spotted 25 sacks Class C Neat cement. POOH. WOC 4 hours. RIH and tagged cement at 67'. Rigged up wireline. RIH and perforated 4-1/2" casing at 40'. POOH and rigged down wireline. Nippled down BOP. Shut well in for night.

6-25-2002 - Spotted 30 sacks Class C Neat cement down 4-1/2" casing and up through 8-5/8" casing. Rigged down pulling unit and plugging equipment. Installed regulation abandon-

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Agent for BCM & Associates DATE 6-27-2002

Type or print name Rusty Klein

Telephone No. 746-6565

(This space for State use)

APPROVED BY [Signature]

TITLE Field Rep

DATE JUL 31 2002

Conditions of approval, if any.