

Form 9-331
(May 1963)UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TR. STATE
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-0305188

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Dry		7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Hanagan Petroleum Corporation		8. FARM OR LEASE NAME Pecos River
3. ADDRESS OF OPERATOR P. O. Box 1737, Roswell, New Mexico 88201		9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980' FNL & 660' FEL		10. FIELD AND POOL, OR WILDCAT Wildcat
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 34-18S-27E
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3419' KB		12. COUNTY OR PARISH Eddy
16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data		13. STATE N. Mex.

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

9/23/72: TD 10,067, Well temporarily abandoned - plugs in manner.

Plug and abandoned temporarily 12/27/72 following manner.
 8-5/8 set @ 3740 w/cement plug set @ 3700-3800 and all plugs set below.
 100' plug will be set @ top stub + 100' @ 260 to 360 in & out of surface
 12-3/4 set @ 310' & 10 sx. plug @ surface & install appropriate dry hole
 marker (no 12-3/4" csg. will be pulled, cmt. circ. on it). Will start
 job 12/27/72.

RECEIVED

DEC 26 1972

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Agent

DATE 12/21/72

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

JAN 2 1973
 R. L. BEEKMAN
 ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side