

BILL GRESSET

10-3-74

TOC - @ 859 leaking

to @ 0 to top ut @

1038 + If can pump thru

sq. If not drill out

sq.