NO. OF COPIES RECEIVED 3		D
DISTRIBUTION		Form C-103 Supersedes Old
SANTA FE /	NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103
FILE ,		Effective 1-1-65
U.S.G.S.	RECEIVED	5a. Indicate Type of Lease
LAND OFFICE		State Fee X
OPERATOR /	SEP 1 9 1973	5. State Oil & Gas Lease No.
	OE1 1 / 13/3	5. State Off & Gda Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS TO THE COUNTY OF THE C		
(DO NOT USE THIS FORM FOR PROI USE "APPLICATI	POSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. ON FOR PERMIT - (FORM C-101) FOR SUCH PROPOSEM 12 CENTER	
1.	Common Control Storm Proposition Proposition	7. Unit Agreement Name
OIL GAS WELL	OTHER- Dry hole	
2. Name of Operator	513 11010	8, Farm or Legse Name
Coquina Oil Corporation	n	Hoffman Com.
3. Address of Operator		9. Well No.
200 Bldg. of Southwest	, Midland, Texas 79701	1
4. Location of Well	, illurating rexus 75701	10. Field and Pool, or Wildcat
UNIT LETTER B 660 FEET FROM THE NORTH LINE AND 1980 FEET FROM		1
UNIT LETTER	FEET FROM THE NOT CIT LINE AND 1900 FEET FROM	Und. W.Atoka, Morrow(Ga
Fac+	ון וסכ פרד	
THE LUSC LINE, SECTION	N 11 TOWNSHIP 18S RANGE 25E NMPM.	
	15, Elevation (Show whether DF, RT, GR, etc.)	
	G.L. 3477	12. County
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	
OTHER		
OTHER		
12 Describ Formed a Carolina Company (Clark and 2) and a clark		
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.		
Drilled 7 7/8" hole to 8,635' on 9-11-73. DST summary attached. Ran electric logs. Ran		
drill pipe open-ended and set 35 sx. cement plug from 8,450-8,350'; 6,950-6,850'; 5,425-		
, J		
5,325'; 4,100-4,000'; and 2,050-1,950'. Set 50 sx. cement plug from 1,300-1,200'. Cut		
off 8 5/8" wellhead and set 10 sx. plug in top of 8 5/8". Welded on DHM. Set 5 sx.		
The state of the s		
plugs in rathole and mousehole. Job complete 9-13-73.		
Frage in the reserve and medically confidence of 10 70.		
1140 habi - 13 3/6 - 300 - Cine,		
Caring left in hole - 13 3/6"- 500 - Cire. 8 3/6"- 1250 - Cire.		
\mathcal{O}	0/8-10	
18. I hereby certify that the information a	bove is true and complete to the best of my knowledge and belief,	
SIGNED ACCURATION SUPPRINTED THE SUperintendent our 9-18-73		
SIGNED / There is the	TITLE Superintendent	DATE 9-18-73
D D - C	The second secon	· · · · · · · · · · · · · · · · · · ·

OIL AND GAS INSPECTOR

din.