Form 3160-5 (June 1990)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

Oil Cons.
N.M. DIV-Dist. 2 FORM APPROVED
1301 W. Grand Avenusapires: March 31, 1993
Artesia, NM 882149 Designation and Serial No.
NM - 02426

SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to deepen or reentry to a different reservoir  Use "APPLICATION FOR PERMIT-" for such proposals			6. If Indian, Allottee or Tribe Name IT.
	SUBMIT IN T	RIPLICATE	7. If Unit or CA, Agreement Designation
1. Type of Well  Oil  Well  Other  2. Name of Operator  Yates Petroleum Corporation  3. Address and Telephone No.  105 S. 4th St. Artesia, NM 88210  4. Location of Well (Footage, Sec., T., R., M., or Survey Description)  880' FSL, 1480' FEL, SEC. 9, T18S, R29E, Unit O SWSE			8. Well Name and No.  WLHU Gas Unit Tract 19A-2  9. API Well No.  30-015-977 2097  10. Field and Pool, or Exploratory Area  Loco Hills - Q-GB -SA  11. County or Parish, State
10	OUEQU ADDDODDIATE DOW > TO	INDICATE MATURE OF MOTION REPORT	Eddy County, NM
12. 	The state of the s	INDICATE NATURE OF NOTICE, REPORT,	
	TYPE OF SUBMISSION	TYPE OF ACTION	
	<ul><li>Notice of Intent</li><li>✓ Subsequent Report</li></ul>	Abandonment  Recompletion  Plugging Back	Change of Plans  New Construction  Non-Routine Fracturing
	Final Abandonment Notice	Casing Repair  Altering Casing	Water Shut-Off Conversion to Injection
directio	onally drilled, give subsurface locations and measured an	Other  pertinet details, and give pertinent dates, including estimated da nd true vertical depths for all markders and zones pertinent to thi	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)  te of starting any proposed work. If well is s work.)*
direction 1. 9/4 2. 9/4 3. 9/4 4. 9/4 5. 9/5 6. 9/5	be Proposed or Completed Operations (Clearly state all ponally drilled, give subsurface locations and measured an /01 Set 5 1/2 CIBP @ 2462 /01 RIH tagged CIBP circulate well w/9.8 mu /01 Spot 50 sx. class"C"neat cmt from 2462' /01 Spot 20 sx. class "C"neat cmt @ 1029 /01 RIH tagged cmt @ 741' /01 circulate cmt. from 393' to surface w/ 40 in Cut off well head install dry hole marker	pertinet details, and give pertinent dates, including estimated dated true vertical depths for all markders and zones pertinent to this does not all to 1968.  Sx. class "C" neat cmt.	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)  te of starting any proposed work. If well is
direction 1. 9/4 2. 9/4 3. 9/4 4. 9/4 5. 9/5 7. 9/6 7. 9/6	onally drilled, give subsurface locations and measured an /01 Set 5 1/2 CIBP @ 2462 /01 RIH tagged CIBP circulate well w/9.8 mu /01 Spot 50 sx. class"C"neat cmt from 2462' /01 Spot 20 sx. class "C"neat cmt @ 1029 /01 RIH tagged cmt @ 741' /01 circulate cmt. from 393' to surface w/ 40 s	pertinet details, and give pertinent dates, including estimated dand true vertical depths for all markders and zones pertinent to this does not seem to the seem of the seem o	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)  te of starting any proposed work. If well is s work.)*