

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
310 Old Santa Fe Trail, Room 206
Santa Fe, New Mexico 87503

WELL API NO.

30-015-21106

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☐

GAS
WELL ☒

OTHER ☐

2. Name of Operator

Lynx Petroleum Consultants, Inc.

3. Address of Operator

P.O. Box 1979, Hobbs, NM 88241

7. Lease Name or Unit Agreement Name

Kaiser Com.

8. Well No.

1

9. Pool name or Wildcat

Red Lake Penn

4. Well Location

Unit Letter C : 660 Feet From The North Line and 2020 Feet From The West Line

Section 18

Township 18S

Range 27E

NMPM

Eddy

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3287' GR

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set CIBP @ 8980'. Spotted 35' cement on top of CIBP. 2/1/95

2. Cut and pulled 5 1/2" casing from 5500'.

3. Spotted 25 sxs cement plug 6250-6010'. Spotted 50 sxs cement stub plug 5550-5180' (tagged plug @ 5180'). OIL CON. DIV. DIST. 2

4. Spotted 30 sxs cement plug 4410-4310'. Spotted 50 sxs cement 2045-1919' (tagged plug @ 1919').

5. Spotted 30 sxs cement plug 1245-1100'. Spotted 30 sxs cement plug 250-100'. Spotted 10 sxs cement surface plug.

6. Cut off wellhead. Installed dry hole marker.

7. Cleaned location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Marc Wise

TITLE

President

DATE

11/17/95

TYPE OR PRINT NAME

Marc Wise

TELEPHONE NO. 505-392-6950

(This space for State Use)

APPROVED BY

[Signature]

TITLE

[Signature]

DATE

12/18/95

CONDITIONS OF APPROVAL, IF ANY: