

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

MAY - 8 1992

O. C. D.

WELL API NO.

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

B-10456

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL  
WELL ☒

GAS  
WELL ☐

OTHER

2. Name of Operator

Anadarko Petroleum Corporation

3. Address of Operator

P.O. Drawer 130, Artesia, New Mexico 88211-0130

4. Well Location

Unit Letter I : 1330 Feet From The South Line and 10 Feet From The East Line

Section

14

Township

18S

Range

27E

NMPM

Eddy

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3514.3' GR

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: Add Queen perfs ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rig up pulling unit.
2. Pull rods and tubing.
3. Perforate Queen (Penrose) 1463' - 1481' @ 2 SPF.
4. Straddle new perfs.
5. Acidize w/2000 gals 7½% NEFE & ball sealers.
6. Swab test.
7. Frac Queen zone.
8. Pull packer & bridge plug.
9. Put back on pump (commingling Queen w/ Grayburg).

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

*Jerry E. Buckles*

TITLE

Area Supervisor

DATE

May 8, 1992

TYPE OR PRINT NAME

Jerry E. Buckles

505  
TELEPHONE NO. 748-3368

(This space for State Use)

ORIGINAL SIGNED BY  
MIKE WILLIAMS  
SUPERVISOR, DISTRICT II

MAY 11 1992

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

ARTESIA STATE UNIT #5-1  
 U. L. I, 1330' FS\* 10' EL  
 Sec 14-185-27E  
 EDDY COUNTY, NEW MEXICO

Spudded 2-5-75

LCE 92' →  
 +  
 Dry Drilled  
 to 303'

8 5/8" @ 285'  
 Cmt'd w/ 210 sxs H  
 (Did Not Circ)  
 Redimix w/ 6 yds.

Casings:

8 5/8" - 24#, K-55  
 4 1/2" - 10.5#, K-55  
 R-2

Queen (Penrose) : 1463-81

Loco Hills : 1718-22  
 1727-31

4 1/2" @ 1997'  
 Cmt'd w/ 300 CM  
 4% gel + 220 H<sub>2</sub>O  
 .2% D-65, 5# salt,  
 10# sand  
 (Cmt Circ - 50%) TD 2000'

Grayburg : 1795-98  
 1827-30  
 1837-42  
 1852-56  
 1868-72  
 1895-98  
 1900-02

2010' KB

GRSB  
 4/24/92