## OH CONSERVATION DIVISION

	·	
WD. OF COMIES ACCEIVED	L	
DISTRIBUTION		
ANTA FE	1	
ILE	1	
.3.0.3.	1	
AND OFFICE		

40, 47 (67)	* *************************************	OIL CONSERVA	TION DIVISION			
DISTAIL	NOITUE	P, O, BO.	Form C-103 - Revised 10-1-78			
JANTA FE		SANTA FE, NEW	MEXICO 87501 DEC 18			
U.S.G.S.			O. C.	5a. Indicate Type of Lease  State Foo Y		
LAND OFF	CE		<del>-</del>	State State Off & Gas Lease No.		
OPERATOR			ARTEGIA, O	Tips, State Off & Gas Lease No.		
	CHNDDA	NOTICES AND DEDOOTS ON	WELLS			
(00 NOT U	SE THIS FORM FOR PROPOS	NOTICES AND REPORTS ON ALS TO DRILL OR TO DEEPEN OR PLUG B	IACN TO A DIFFEHENT RESERVOIR.			
				7, Unit Agreement Name		
MELL	WELL X	OTHER-				
, trame of Operati				8. Farm or Lease Name		
DAVID FASK				Bradshaw		
Address of Ope		Puilding Midland Toys	20701	9. Well No.		
Location of Wel		Building, Midland, Texa	5 /9/01	10. Field and Pool, or Windcat		
	G 16	550 FEET FROM THE East	1980	Atoka		
UNIT LETTER .		FEET FROM THE	LINE AND FEET FR			
Nort	th recrea	2 18-S	RANGE 26-E NMI			
186	tine, section					
		15. Elevation (Show whether	DF, RT, GR, etc.)	12. County		
		3290' GR		Eddy ())))))		
	Check App	propriate Box To Indicate N	Nature of Notice, Report or C	Other Data		
	NOTICE OF INT	ENTION TO:	SUBSEQUE	NT REPORT OF:		
	Г	Г				
PERFORM REMEDIA	Ä	PLUG AND ABANDON	COMMENCE DRILLING OPHS.	ALTERING CASING		
TEMPORARILY ABA	7-1	CHANGE PLANS	CASING TEST AND CEMENT JOB	PLUG AND ABANDONMENT		
THE OF ALTER CA	3144 [_]		OTHER			
OTHER						
The state of the s	and as Completed Opera	stone (Charle state all national day	inite and aire partinent dates includ	ing estimated date of starting any proposed		
work) SEE RI		tions (crearly state on perimen, der	ans, and give periment dates, merad	ing estimated date of starting any proposed		
10-31-80	Piggod up Otio	s wireline truck & set	"N" plug in "N" profil	o ninnlo A 8612! VR		
10-31-00	Kigged up our	, whethe cluck α sec	n plag III n proffi	e hippie e doiz kb.		
11-3-80	11-3-80 Moved in & rigged up pulling unit, removed Christmas tree and installed BOP's,					
		down 2-7/8" N-80 EUE 8		,		
	•					
11-4-80	Loaded hole with 3% KCl water, perforated Penn Lime from 8122'-8134' (13 - 0.39"					
	holes) & 8073'-8080' (8 - 0.39" holes). RIW w/Otis 4-1/2" x 2-3/8" P.L. packer & TOSSD on 2-3/8" N-80 4.7#/ft EUE 8rd thd tubing, set pkr @ 7991.51'.					
	& 1022h on 5-	3/8 N-80 4./#/IL EUE 8	sra tha tubing, set pkr	0 /991.51 .		
11-5-80	80 Swabbed well dry, acidized w/2500 gals 15% N.E. acid, swabbed fluid down to 6100'					
11 3 00		3 bbls load water & ac		364 11414 domin 00 0100		
			3			
11-6-80	Swabbed fluid down to 7900' w/no gas & no fluid entry.					
44 7 00	Set "N" plug in Otis P.L. pkr 7992', released TOSSD & pulled 2-3/8" tubing.					
11-7-80	Set "N" plug	in Utis P.L. pkr 7992	, released 10550 & pull	ed 2-3/8" tubing.		
1500 2+	tached continua	tion)				
(see at	tached Continua	crony				
I hereby certif	y that the information ab	ove is true and complete to the best	of my knowledge and belief.			
137	11-4-11/	/ .		10 10 00		
TICHER TO	and 116	Come Ro	bert H. Angevine, Agent	DATE 12-16-80		
*. <del>717</del>						
	Ja G. Gines		Websyksof, Doordoo a	DATE TO SEE		
PRAOVED BY	0,000		<del> </del>	PATE AND A STATE OF THE PATE O		